

## 20/20 HOME INSPECTIONS

40 Stockell Crescent  
Ajax, Ontario L1T 0M4  
Telephone: 416-518-9680

---

### HOME INSPECTION REPORT



**Property Address:**

8 Rusholme Park Cres

**Date of inspection:**

Feb 11th 2019

**Prepared By:**

Pradeep Samaroo, RHI

**20/20HOMEINSPECTIONS**

40 Stockell Crescent  
Ajax, Ontario L1T 0M4  
T: 416-518-9680  
E: pradeep\_samaroo@hotmail.com  
W: [www.2020homeinspections.ca](http://www.2020homeinspections.ca)

---

**Our Vision is Your Peace of Mind**

**Residential and Commercial Property Inspections**  
**Buyers Home Inspections**  
**Inspections for Sellers Prior to Listing**  
**Thermal Imaging**  
**Inspections of Newly Constructed Homes**

## PRE-LIST SUMMARY

Address:  Municipality:  Inspection Date: General Information:  Inspector: Age of House  years. Construction Type:   This house is in  functional condition in comparison to other similar age and size homes in the neighbourhood.On average; a house of similar age/size and quality will cost you  for annual general repairs and on-going maintenance.You will require  (minimum) to address the functional concerns listed in the the report over the next  years.

## MAJOR SYSTEMS - GENERAL DESCRIPTION AND CONDITIONS:

Roofing systems:  Secondary roofing system: Exterior wall systems:  Secondary wall siding:  Windows(general): 

## Electrical Systems

Main service size  amp  Predominant branch wiring: 

## Heating System

Fuel type:  Age of central heating appliance:  years System type: 

## Cooling System

System type:  Age of cooling equipment:  years Approx. tons: 

## Plumbing System

Main supply:  Predominant water lines Interior (general): 

## HOMEOWNER INSURANCE CONCERNS

☐ None Identified  

## REQUIRED REPAIRS/MAJOR SYSTEMS AND COMPONENTS APPROACHING END OF EXPECTED LIFE SPAN

 Time frame  years Budget \$  Time frame  years Budget \$  Time frame  years Budget \$  Time frame  years Budget \$  Time frame  years Budget \$  Time frame  years Budget \$ ☒  Time frame  years Budget \$ ☒  Time frame  years Budget \$ ☐  Time frame  years Budget \$ 

## OTHER RECOMMENDATIONS

☐ 

## ADDITIONAL INFORMATION REQUIRED

☐ 

## SUMMARY

This report should not be considered as a complete home and property inspection. The 20/20 Home Inspections report is prepared for the owner to provide general information about this property. The inspector is available by telephone to any interested party to answer questions about the house. Please read the full report prior to calling the inspector. We are also available to provide any prospective buyer general orientation; helpful maintenance tips and improvement consulting for a fee. This general review inspection is essential to compare your expectations, intended use and special needs with the realities of the house. Interested parties should be advised that; without this general review our obligation and liability can only remain with the seller.

## PRELIMINARY BUILDING INSPECTION REPORT

Property Inspected  Municipality

Inspection Date  Time  Inspector

## SUMMARY (GENERAL COMMENTS)

In comparison to other homes of similar vintage in the vicinity the functional condition of this building/dwelling is; .

Recommended improvements or repairs to the building/dwelling have been addressed in the report.

It is suggested that the highlighted concerns be considered priorities.

**Please be advised that failure to address concerns promptly may result in additional problems and/or consequential damages.**

	MINOR	MAJOR		MINOR	MAJOR
	REPAIRS	REPAIRS		REPAIRS	REPAIRS
Roofing	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Structure	<input type="checkbox"/>	<input type="checkbox"/>
Exteriors	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Electrical	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Interiors	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Heat/Cool	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Maintenance	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Plumbing	<input type="checkbox"/>	<input checked="" type="checkbox"/>
<input type="text"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="text"/>	<input type="checkbox"/>	<input type="checkbox"/>

Comments:

- The preliminary inspection report issued by the inspector is prepared with reasonable skill and care. This consulting service is limited to the physical evidence that was visually accessible at the time of the inspection. This report is not transferable to anyone other than the client as this report does not include the verbal information imparted by the inspector which is vital to fully understand the service and contract.
- The required repairs to the building include but are not limited to what is reported herein due to the limitations and restrictive nature of the visual inspection. The client is hereby warned that not all deficiencies will be discovered. At best 80% of the first year repairs should be revealed; not 100%. Determining the presence of mold, fungi and other indoor air quality contaminants are specifically not included.
- The inspector's role is principally educational; to provide you with a better understanding of the building. We will not detect all problems.
- The preliminary inspection is partially designed to reduce your risk of buying an older home. However we cannot eliminate this risk. The inspector/inspection firm will not assume any of your risk in buying an older property. Further inspections by specialists are required.
- The client is advised to annually budget at least 1% of the building's value for general maintenance and unforeseen repairs.
- The client is warned that resultant damages may occur to the building systems or components if the recommended repairs in this report are not carried out in a timely manner. This is especially the case in matters concerning uncontrolled water/vapour.
- Cost estimates if provided in this report are minimums and are intended to be a rough guideline only. Estimates are based on the most cost effective solution to address the problem and will not include betterment. Obtain accurate cost estimates from contractors immediately.
- The preliminary inspection does not cover code compliance issues set by governments or other regulatory authorities.
- The preliminary inspection does not take into account manufacturer's recalls and eligibility for mortgage insurance, building or homeowners insurance.
- The preliminary inspection process is conducted in a fair and impartial manner. Accordingly this report is not provided as an aid for negotiation in a real estate transaction. We do not overstate or under value any issue to benefit any party.
- The purchaser is advised to ask the property owner if they are aware of any defects that would not normally be detected by a visual inspection. The purchaser is advised to revisit the property before closing to verify that functional conditions remain unchanged or retain the inspector for this task.
- The client hereby acknowledges they are contractually obliged to contact the inspector immediately to arrange a site visit at no extra expense in the event of an unforeseen and/or unreported problem or upon receiving a conflicting opinion and prior to any corrective work.

**I have read this contract and report and am aware of the limitations of the inspection process. I accept this report and supplements according to the conditions as stated herein. I am aware that the fee paid for this inspection is for professional time and is not a guarantee of present or future conditions and is not an insurance policy of any kind. I am aware that I can retain the inspector to re-evaluate the property prior to closing for evidence of new water leaks and/or items not previously inspected due to seasonal limitations for an additional fee.**

Name of Client  (Bus.)  (Res.)

Current Address  Other

E-mail:

## GENERAL CONDITIONS/SPECIAL SITUATIONS & LIMITATIONS

The primary purpose of the inspection and report is to educate the prospective purchaser/owner about the general condition of the building. Repair and cost effective improvement advice is provided to increase this understanding. It is not a contractual obligation nor is it possible for the inspector to identify all potential problems solely on the basis of a visual examination. 80% of first year repairs should be revealed: not 100%.

## DEFINITION OF TERMS USED IN THE PRELIMINARY INSPECTION REPORT:

<b>Functional</b>	(1) system was performing its' intended purpose at the time of the inspection, no significant loss of functionality
<b>Monitor and/or Maintenance</b>	(1) item is marginal; will require future repair or replacement. Owner is advised to monitor. (2) preventative maintenance repairs are required by property owner.
<b>Minor Repair</b>	(1) minor repair is recommended; cost should not exceed \$3000.00 and/or repair is not urgent.
<b>Major Repair</b>	(1) major repair is recommended; cost will exceed \$3000.00. Obtain contractor's estimates immediately.
<b>Good Condition</b>	(1) no defects were discovered that should require repair within the first six months, no significant loss of functionality

**Note: Limitations of a visual inspection and visually accessible physical evidence are in effect.**

<b>Fair Condition</b>	(1) system or component is performing its intended purpose; but due to its age can fail at any time.
<b>N/A</b>	(1) not applicable/not accessible/not inspected/not installed or does not pertain to the subject property.
<b>(?)</b>	(1) performance/future performance of system or component is unpredictable. Further review is required.

The inspector's objective during the summary portion of the inspection is to discuss the significant aspects of their findings. There is no time limit on these discussions. Ask as many questions as you like to ensure we have addressed your concerns. The inspection process is a two-part system: the verbal survey and the report. This report is not transferable to third parties as it will not clearly convey the information herein.

## WEATHER CONDITIONS

- ☒ **Snow/** rain/  limited the extent of the exterior inspection. ☒ **Roof/ grade/ walkway/** decks were snow covered.
- ☐ Absence of recent heavy rainfall limited scope of basement foundation inspection.
- ☒ The outdoor temperature was too low to safely test the air conditioning system(s)/distribution systems and summer comfort.
- ☐ The outdoor temperature was too high to sufficiently test the central heating system/distribution systems and winter comfort.

**Weather conditions during inspection:** ☐ Rainy ☐ Snow ☐ Clear ☒ Cloudy ☐ Windy **Temperature**

## INACCESSIBILITY

- ☐ Basement/ Garage storage limited access/ visibility. ☐ Excessive storage limited access to:
- ☐ Areas/ systems/ work in progress not fully visually inspected:
- ☐ Other specific limitations:
- ☐ Plumbing system winterized (not fully inspected) ☐ Inspection of plumbing limited due to recent non-usage.
- ☐ Building substantially furnished ☐ Building occupied ☐ Building vacant/ partially ☒ Building unoccupied

## RENOVATIONS/REMODELLING

Some recommendations contained in this report are based on the intent of the client that upgrades will be done to the following:

- ☐ Exterior ☐ Addition ☐ Kitchen ☐ Bathroom(s) ☐ Basement

## GENERAL/ORIENTATION

- ☐ For reference purposes the front of the building is facing: ☐ north ☒ south ☐ east ☐ west
- ☐ Seller has warranted the following:
- ☐ Further inquiries to seller is recommended regarding:

## TYPE OF INSPECTION/TRANSACTION

- ☐ Pre-purchase inspection ☒ Pre-sale inspection ☐ Newly built house inspection ☐ Post-purchase inspection
- ☐ Home owners inspection ☐ Estate sale ☐ Power of sale ☐ Private sale ☐ Pre-lease/rental inspection ☐ Pre-offer inspection

## ATTENDANCE

- ☐ Buyer/client not present at inspection ☐ Client partially attended inspection ☐ Client fully attended inspection
- Also in attendance: ☐ Seller ☒ Seller's agent ☐ Buyer's agent

## EXCLUSIONS

- ☒ The testing of swimming pools & related equipment is beyond the scope of our visual inspections.
- ☒ Exterior/common elements are the responsibility of the the condominium corporations. Review particulars with legal counsel.
- ☒ Appliances/central vacuum systems/trees/heat exchangers/flue interiors/outbuildings/security system/intercom/spas/wood destroying insects/vermin and animals/underground storage tanks/sub-grade plumbing drains/environmental testing/UFFI/mold and other indoor air quality contaminants/ window air conditioners/asbestos containing material/septic tanks/wells/marine structures and other items not specifically mentioned in the report are not included within the scope of this inspection. We do not disassemble equipment/bore holes into walls/floors and ceilings/move furniture and boxes/lift up carpets.

## COST ALLOWANCES/TIME FRAMES AND SHORT TERM COURSE OF ACTION

### YOUR EXPECTATION LEVEL

We have included this summary to help you prepare and budget for future work. Please be cautioned that the following noted items represent the minimum amount of work that you will address in the future. Be aware that you may receive opinions from other tradespeople or knowledgeable parties that can vary drastically from our own. In this instance we require you to contact us immediately to seek clarification or request a site inspection at no further expense.

### GENERAL CONDITION AT THE TIME OF THE PRELIMINARY INSPECTION

- ☐ The subject property requires less current repair consideration than the average house/building of similar vintage
- ☒ The subject property requires an average amount of repair consideration compared with other houses/buildings of similar vintage.
- ☐ The subject property requires more current repair consideration than the average house/building of similar vintage.

The average annual repair/maintenance budget for a home/building of similar size and vintage is:

### YOUR MINIMUM BUDGET ALLOWANCE:

- ☐ over the first 0 - 2 years ☒ over the first 0 - 5 Years ☐ over the course of

To address the functional concerns listed below you must budget at the very least the following amount:

- ☐ \$2000-\$5000 ☐ \$5000-\$10000 ☐ \$10000-\$15000 ☒ \$15000-\$20000

### AREAS REQUIRING CONSIDERATION

- |   |  |   |   |   |  |
|---|--|---|---|---|--|
| Roofing Systems:  | <input checked="" type="checkbox"/> Roof Coverings | <input checked="" type="checkbox"/> Eavestroughs/down pipes | <input type="checkbox"/> Overhangs                | <input type="checkbox"/> Chimneys/flashings             | <input type="checkbox"/> Skylights                 |
| Exterior:   | <input type="checkbox"/> Brick/sidings/walls       | <input checked="" type="checkbox"/> Windows/doors           | <input type="checkbox"/> Site drainage            | <input type="checkbox"/> Porches/decks                  | <input type="checkbox"/> Painting                  |
|   | <input type="checkbox"/> Garage/sheds              | <input type="checkbox"/> Driveway/walkway                   | <input type="checkbox"/> Landscaping              | <input type="checkbox"/> Fencing/gates                  | <input checked="" type="checkbox"/> retaining wall |
| Structures:   | <input type="checkbox"/> Crawlspace                | <input type="checkbox"/> Beams/columns                      | <input type="checkbox"/> Floors                   | <input type="checkbox"/> Foundation wall                | <input type="text"/>                               |
| Electrical Systems:   | <input type="checkbox"/> Main service/panels       | <input type="checkbox"/> Lighting fixtures/switches         | <input checked="" type="checkbox"/> Branch wiring | <input checked="" type="checkbox"/> Receptacles/outlets | <input type="text"/>                               |
| Heat/Cool Systems:  | <input checked="" type="checkbox"/> Furnace/boiler | <input type="checkbox"/> Distribution: ducts/rads           | <input checked="" type="checkbox"/> AC system     | <input type="checkbox"/> Filters/humidifiers            | <input type="text"/>                               |
| Plumbing Systems  | <input type="checkbox"/> Main water service        | <input type="checkbox"/> Distribution piping                | <input checked="" type="checkbox"/> Drains/vents  | <input type="checkbox"/> Fixtures/fitting               | <input type="text"/>                               |
| Interiors:  | <input type="checkbox"/> Kitchen                   | <input type="checkbox"/> Basement spaces                    | <input type="checkbox"/> Bathrooms                | <input type="checkbox"/> Attic/roof spaces              | <input type="checkbox"/> Fireplaces                |
|   | <input type="checkbox"/> Walls/ceilings            | <input type="checkbox"/> Floor coverings                    | <input type="checkbox"/> Stairs/railings          | <input type="checkbox"/> Appliances                     | <input checked="" type="checkbox"/> Decorating     |
| <input checked="" type="checkbox"/> General annual & seasonal exterior/interior building maintenance & small repairs <input type="text"/> |  |   |   |   |  |

### YOUR RECOMMENDED COURSE OF IMMEDIATE ACTION:

Please review the preliminary report in its entirety and ask for clarification on any matter. This page must not be relied upon in isolation. Prior to continuing with the next step of the transaction/project consider the issues listed in the report. We advise you to consult with your realtor or lawyer regarding options on how to proceed. Also instruct your lawyer to obtain Title Insurance for you. You should request additional inspections as outlined in the full report to address your special concerns and/or matters that we can not inspect. You must also factor the limitations of the building inspection in your decision making process. 80% of first year repairs should be revealed: NOT 100%. Therefore you must anticipate and budget for the 20% unforeseen deficiencies that will not be discovered by a visual inspection. You must ask the seller for invoices/applicable warranties/plans and/or permits for work completed in the last five years.

- ☒ Consider all deficiencies related to health/ safety issues and uncontrolled water problems as urgent matters.

☐ Further clarification regarding:

is required of the:

is required of the:

- ☒ Further inspection/evaluation is required regarding:

☒ OBTAIN CONTRACTORS QUOTES/REPAIR SPECIFICATIONS ON ANY MAJOR REPAIR NOTED HEREIN IMMEDIATELY.

Major Repair  
Minor Repair  
N/A  
Monitor  
Functional

**METHOD OF ROOF INSPECTION**

☐ Fully accessed (walked on) ☐ At eaves ☒ At ground with binoculars ( too steep/ inaccessible ) **Note: (limitations in effect)**

**LIMITATIONS**

☒ Majority of the above elements were snow/ ice/ frost covered. ☐ Flat roof is covered with gravel/ decking  
☒ Due to the unpredictable and latent nature of roof leaks no assurances or warranty can be provided that your roof will not leak within the approximated expected lifespan stated in this report. Ice damming problems are beyond our ability to predict.

**ROOF COVERINGS TYPE**

☐ Asphalt shingles are the principal roof covering of the building.  
☐ Asphalt shingles cover all sloping roof surfaces of the building.  
☒ Flat roof membrane covers the principal flat roof surfaces of the building.  
☐ is the principal roof covering of the building.  
☐ covers the roof surface at the  
☒ Shingles only cover the roof surfaces at the front of the house.

**ROOF COVERINGS CONDITION (where visible)**

Estimated remaining lifespan of roof shingles/coverings: ☐ NOTE: Estimated lifespan based on visible portion of roof only.

Shingles = 5-8 years ☒ ?

Flat - Unable to observe = years ☒ ?

General condition of flat roof coverings: ☐ Good ☐ Fair ☐ Poor ☒ ? Unable to observe

☐ Current repair is required at:  
☐ Roof covering replacement is required at:  
☐ High probability of replacement of roof coverings within years.  
☐ Repairs/ roofing tune-up is required soon/ before next application of roof coverings ☒ Annual visual inspection required.  
☐ Trim tree branches/ vines away from roof edge. ☐ Tree removal recommended at:  
☒

**ROOF/WALL FLASHINGS & JOINTS (where visible)**

☒ All/most flashings are in ☐ Good condition ☒ Fair condition ☐  
☐ Repair/ replace/ install flashings at:  
☐ Repair/ replace all flashings with next roof covering replacement. ☐ Caulking rec'd at:  
☐ Repairs/ maintenance required before next application of roof coverings: (ie) caulking or tarring

**ROOF DRAINAGE**

**Type:** ☒ Aluminum ☒ Galvanized steel ☐ Plastic ☐ Copper ☐ Lead ☐ Hoppers/Scuppers  
☒ Roof drainage is in: ☐ Good condition ☒ Fair condition ☐ Seasonal cleaning required  
☐ Gutters ☒ Downpipes/ drains require repair/ extending/ painting at:  
☐ Extend downpipe from upper level roof directly into lower gutter/ eavestrough. ☒ Repair loose gutters; nails.  
☐ Extend/ relocate downpipe(s) at corner/ side 4'-6' away from building ☐ Add drainage pads  
☐ Replacement/ Installation of gutters/ downpipes recommended at:  
☐ Gutters & downpipes are approaching end of functional life. ☒ Caulking at leaky joints required.  
☐

**SOFFIT AND FASCIA**

**Type:** ☒ Aluminum ☐ Plywood ☒ Wood ☐ Vinyl ☐  
**Soffit & fascia are in:** ☐ Good condition ☒ Fair condition ☒ Painting of soffit/ fascia required  
☒ Repairs are required/ recommended at: Painting of fascia and soffit at rear addition  
☐ Replacement/ new aluminum cladding of soffit/ fascia is recommended in future. ☐

**SKYLIGHTS ROOF WINDOWS & SOLARIUMS**

**Type:** ☐ Factory built ☐ Home-made (usually of sub-standard quality) ☐  
**Units are in:** ☐ Good condition ☐ Fair condition ☐ Evidence of leakage at:  
☐ Annual maintenance/ caulking recommended. ☐ Repair/ replace:  
☐  
☐ See Additional Comment Page



**EXTERIOR (GENERAL CONDITIONS)**

Major Repair  
Minor Repair  
N/A  
Monitor  
Functional

Approximate age of building is  years. Building has been substantially renovated  years ago. ☐ N/A

**TYPE OF STRUCTURE CONSTRUCTION TYPE OCCUPANCY TYPE**

- ☐ Detached ☐ Wood frame ☒ Single family dwelling ☐ Duplex  
☒ Semi-detached ☐ Brick veneer ☐ Basement apt. added ☐ Triplex  
☐ Row house/fully attached ☒ Solid masonry ☐ Multi-purpose occupancy ☐ Fourplex  
☐ Condominium/townhouse ☐ Wood frame-upper level  ☐ Multiplex  
 ☐ Brick front only

**EXTERIOR WALLS/WALL COVERINGS**

☒ ☐ ☐ ☐ ☐

**Brick/Masonry (inspected at grade level)**

☒ Masonry units & mortar are in: ☐ Good condition ☒ Fair general condition.

☐ Mortar repair; tuck point recommended at:

☐ Brick repair required at:

☐ Non-structural cracks noted which could/ should be repaired. ☐ Repair sills at:

☒ ☐ ☐ ☐ ☐

**Wall sidings (inspected at grade level)**

Type: ☒ Aluminum ☐ Vinyl ☒ Wood ☐ Insulbrick ☒ Asphalt siding- rear addition ☐ Stucco/ EIFS

☐ Good condition ☒ Fair general condition. ☐ Repair required/ recommended at:

☐ New wall coverings/ re-cladding recommended at:

☐ Application of protective coatings ( paint/ stain ) recommended to most/ all wood/ other surfaces.

☐ Caulking/ minor repairs at trimwork:

☒ ☐ ☐ ☐ ☐

**Foundation Wall (above grade)**

Foundation wall is in: ☐ Good condition ☒ Fair condition ☐ Non-structural cracks noted

☐ Requires tuck pointing at:

☐ Requires parging/ repair at:

☒ ☐ ☐ ☐ ☐

**Chimneys**

Type: ☒ Masonry ☐ Metal ☐ Side wall venting ☐ None required ☒ Chimney not in use

☒ Good condition ☐ Fair condition ☐ Requires repair/ tuck pointing ☐ Flue cap recommended

☐ Requires new chimney cap/ drip edge ☐ Requires rebuilding/extending ☐ Remove obsolete chimney

☒ ☐ ☐ ☐ ☐

**Exterior Doors**

Exterior doors at: ☒ Front ☐ Side ☒ Rear are in: ☐ Good condition ☒ Fair condition

☐ Repair/ replace:

☐ Install storm/ screen door at:  ☐ Repair/ replace hardware at:

☐ Upgrade/ caulking/ painting ☐ Upgrade weather stripping ☐ Upgrade locks at:

☒ ☐ ☐ ☒ ☐

**Windows (General)**

Material Type: ☒ Aluminum ☒ Wood ☐ Vinyl trim  ☒ Wood/ aluminum storms

Predominant styles: ☐ Single/Double-hung ☐ Casement ☐ Sashless ☒ Horizontal sliding

Windows are in: ☐ Good condition ☒ Fair condition ☒ Upgrade caulking/ painting

☐ Storm/ screen systems are recommended to be upgraded at:

☐ Repair/ replace window frame/ sills at

☒ Window refurbishing/ replacement recommended:

☒ ☐ ☒ ☐ ☐

**GRADING/SITE DRAINAGE/RETAINING WALLS**

☐ Good condition ☒ Fair grading conditions exist alongside the foundation(s) of the building.

Grading conditions require improvement at: ☐ Front ☐ Rear ☐ Side ☐ Patio/ walkway slopes toward wall

Retaining walls are in: ☐ Good condition ☐ Fair condition

☒ Retaining walls require repair/ replacement at:

Window wells are in: ☐ Good condition ☐ Fair condition

☐ Window well repair/ install at:

☒ See Additional Comment Page

**EXTERIOR (GENERAL CONDITION) continued**

Major Repair  
Minor Repair  
N/A  
Monitor  
Functional

**GARAGE/OUTBUILDING/CARPORT**

**Attached Garage** ☐ Good condition ☐ Fair condition ☐ Poor condition

☐ Gas proofing measures of common walls with house required; provide gas seal. Repair holes in walls/ ceilings.

☐ Entry door into dwelling requires self-closing device /repair self-closure. ☐ Weather stripping/ caulking required to door/ frame.

**Detached Garage** ☐ Good condition ☐ Fair condition ☐ Poor condition/ Remove

**Structure type:** ☐ Wood Frame ☐ Solid Masonry ☐ Brick Veneer ☐ Repairs to walls required

**Roof Coverings**

☐ Good condition ☐ Fair condition ☐ Replace roof coverings soon ☐ Eavestroughs recommended/ repair/ install

☐ Caution: Underground/ overhead wires supplying power to garage/ shed. ☐ Electrical power to garage is recommended

☐

**Overhead Door Operation** ☐ Good condition ☐ Fair condition ☐ Requires repair/ replacement/ painting

**Automatic Door Operation** ☐ Install dedicated receptacle for garage door opener; avoid extension cord use.

☐ Good condition ☐ Fair condition ☐ Requires repair/ replacement ☐ Adjust/ no auto-reverse

**WALKWAYS/DRIVEWAYS**

☐ Good condition ☒ Fair condition ☐ Replacement of driveway/ walkway recommended.

☐ Repair work required/ recommended at:

**PORCHES/DECKS/BALCONIES (egress to exterior)**

**Location:**  **Type:** ☒ wood ☐ masonry ☐ concrete ☐ steel ☐ unable to access under deck

Structural supports: ☒ Good condition ☐ Fair condition ☐

Decking: ☒ Good condition ☐ Fair condition ☐

Steps/stairs: ☒ Good condition ☐ Fair condition ☐

Guards/handrails: ☐ Good condition ☒ Fair condition ☐ Guardrails low/ spacing unsafe/ repair/ missing

**Location:**  **Type:** ☐ wood ☐ masonry ☐ concrete ☐ steel ☐ unable to access under deck

Structural supports: ☐ Good condition ☐ Fair condition ☐

Decking: ☐ Good condition ☐ Fair condition ☐

Steps/stairs: ☐ Good condition ☐ Fair condition ☐

Guards/handrails: ☐ Good condition ☐ Fair condition ☐ Guardrails low/ spacing unsafe/ repair/ missing

Handrail/guardrail recommended alongside steps at:

☐

**EXTERIOR PLUMBING CONDITIONS** ☒ Winterized/ could not test.

**Garden hose connection location:** ☐ Front ☐ Rear ☒ Side ☐ Garage ☐ None ☐

☐ Good condition ☒ Fair condition ☐ Repair/ replace at:

**Main vent stack(s)**

☒ Good condition ☐ Requires repair/ extending from roof

☒ Good clearance from windows/ doors ☐ No evidence of vent stack for plumbing system visible.

**EXTERIOR ELECTRICAL CONDITIONS**

**Exterior plug receptacle location:** ☐ Front ☒ Rear ☐ Side ☐ Garage ☐

☐ Good condition ☒ Fair condition ☐ Requires weatherproof cover ☐ Receptacle not grounded

☐ Requires repair/ replacement at:  ☐ None provided. Installation of GFCI receptacle recommended.

☒ All/ most exterior receptacles are required to be replaced with GFCI type. ☐ Rework exposed cabling at exterior walls

**Lighting location:** ☒ Main entrance ☐ Side entrance ☒ Rear entrance ☐ Garage ☐

**Fixture(s) are in:** ☐ Good condition ☒ Fair condition ☐

☒ Repair/ replace at:  ☐ Installation recommended at:

**Service entrance: (electrical cables feeding house from street transformer)**

☒ Overhead entrance ☐ Underground/lateral entrance

☒ Mast head conduits/ meter base properly affixed to building. ☐ Repairs are required at

☐

☐ See Additional Comment Page



## PREVENTION AND CONTROL OF BASEMENT AND FOUNDATION LEAKS

A leaky basement is one of the most common of all house problems. We must caution you that there is a possibility that leaks can develop in your basement at any time. **We cannot contract with you that previous leaks can be detected or future leaks can be predicted.**

During the inspection exterior conditions were observed which can contribute to basement leaks. Preventative maintenance can greatly reduce the likelihood of rain water leaking through your foundation. The items listed below are primary causes of basement leaks. Please ensure that these items are properly maintained and functional at all times. A resultant effect of continual basement leaks will be the development of mold. Mold in houses can be extremely detrimental to the health of the occupants.

### CAUSES OF BASEMENT LEAKS and What YOU CAN DO TO HELP REDUCE YOUR RISK OF FUTURE LEAKS

The items checked below require either remedial action and/or regular maintenance.

- ☐ Improper grading. Ensure that the ground slopes away from your house.
- ☐ Patios/ walkways slope towards house.
- ☐ Lower grade level at:
- ☐ Inadequate or faulty eavestroughs and downpipe. You should periodically review your rainware during heavy rain to ensure proper function.
- ☒ Dirty/ clogged eavestroughs. Most eavestroughs need to be cleaned twice a year.
- ☒ Inadequate downspout extensions. Downspouts should be extend 4 to 6 feet (1 to 2 metres) away from the house.
- ☐ Relocation of downpipes required at:
- ☐ Faulty downspout connection to rain water leader (at grade level).
- ☐ Probable/ possible deficient or clogged rain water leader (below grade). Disconnect and extend.
- ☐ Non-structural cracks or faults in the foundation wall.
- ☐ Improperly installed window wells.
- ☐ Install window wells at:
- ☐ Porous basement window sill or openings. ☐ Vulnerable door sills at:
- ☐ Improperly sealed through-wall penetrations or wall flashings.
- ☐ Large tree close to the house. Tree roots could adversely affect the foundation.
- ☐ Raised flower bed should be sloped away from the house.
- ☐ Driveway slopes towards house; driveway is in poor/ fair overall condition.
- ☐ Poor improper drainage conditions are present on neighbouring/ adjacent properties
- ☐ Underground sprinkler system outlet is positioned too close to the house.
- ☐ Improperly installed/ clogged areawell drain or catch basin. Must be kept clear at all times.
- ☐ Install areawell drain at:  ☒ Back water valve recommended.
- ☐ Back-up pump/back-up battery or power control for sump pump required.
- ☐
- ☐ Probability of foundation leaks should the above not be remediated and/or kept in good state of repair at all times: ☐ HIGH ☐ MEDIUM ☐ LOW
- ☐ Dehumidifier use in basement during spring/summer is required.
- ☐ You are advised to revisit the property before closing to check for any evidence of foundation leakage or retain our company for this task.

**Review the above checklist should leakage ever occur. This list represents the most probable cause(s) of leaky basements. If you have made the above corrections and leakage persists call us - your inspection company. It is our experience that some basement leaks can be corrected or greatly alleviated without excavation and/or expensive weeping tile replacement.**

### FOUNDATION MATERIAL TYPE CHARACTERISTICS

- ☐ Stone foundations are very porous. Localized exterior excavation is recommended in the event of leakage.
- ☐ Concrete block foundations are very vulnerable to water penetration as there are porous joints around every block. Should leakage occur the entire wall face in question is recommended to be excavated.
- ☐ Brick foundations are very absorbant and will lead to very damp and humid basement spaces. Should leakage occur localized exterior excavation is recommended.
- ☐ Poured concrete foundations in houses 50 years old or newer can be corrected by the crack injection method. Houses that are 50 years or older must be judged on a case to case basis.

**EVIDENCE OF COMPLETE WATERPROOFING MEMBRANE AROUND FOUNDATION WALLS:** ☐ Yes ☐ No ☐ ?

- ☐ Please note that if dry basement living conditions are desired the basement foundation wall must be completely waterproofed at the exterior.
- ☐ It is a certainty that a basement which is not waterproofed coupled with poorly maintained site/roof drainage will develop leaks within the next 5 years.
- ☐
- ☐ See Additional Comment Page

**EXTERIOR (GENERAL CONDITIONS) COMMENT PAGE**

Retaining wall at the rear of the property appears th be constructed of various materials and may be susceptible to  
collaspe without ongoing repairs

Front porch roof- there is a slight slant on the structure of the porch roof- examination of the porch didn't indicate any settling or movement of the structure. It appears that the cloumn on the left side when it was rebuilt was made 1 coarse of brick higher than the other column.

Major Repair  
Minor Repair  
N/A  
Monitor  
Functional

**LIMITATIONS:**

- ☐ Substantially/partially finished basement/ crawlspace limited observations.
- ☒ Due to the unpredictable and latent nature of basement leaks no assurances or warranty can be provided that your basement will not leak in the future. We caution you that it is common for basement leaks to develop at any time in the future where no such leaks existed in the past.

**We cannot detect previous leaking or predict future leaking.**

- ☐ We are unable to detect existence or type of mold at interior space. Further investigation is recommended.

**FOUNDATION CONSTRUCTION TYPE**

- ☒ Continuous foundation ☐ Masonry/ wood piers ☐ Slab on grade ☐ Wood beam on grade

**ACCESS/BASEMENT TYPE**

- ☒ Full basement ☐ Crawlspace ☐ Basement & crawlspace combination ☐ Crawlspace fully/partially accessed
- ☐ Crawlspace is interconnected with adjacent dwelling ☐

**FOUNDATION MATERIAL TYPE**

- ☐ Brick ☒ Stone ☐ Concrete block ☐ Poured concrete ☐ Preserved wood foundation
- ☐ Foundation wall interiors not accessible for visual inspection. ☐ Load-bearing components not visually accessible.
- ☐ Non-structural cracks were observed which could be a source of future water penetration.
- ☐

**EXTENSION/ADDITION** at the  is supported with a different foundation type than the main building.

- ☒ Continuous concrete ☐ Masonry/ wood piers ☐ Slab on grade ☐ Wood beam on grade
- ☐ Crawlspace ☐ Full basement ☐ No visible accessibility ☐ Access to crawlspace is recommended.
- ☐ Repairs/ improvements are required at:

**INTERIOR COLUMNS & BEAMS/INTERIOR LOAD SUPPORTS (BASEMENT LEVEL)****Columns & Walls:** ☐ Wood ☐ Steel ☐ Masonry ☐ Not visible**Beams:** ☐ Wood ☐ Steel ☐ Paralam/ Engineered wood ☐ Not visible**Support system members are in:** ☐ Good condition where visible ☐ Fair condition where visible☐ Repairs to support load are required at: **FLOOR (BASEMENT)**

- ☒ Concrete ☐ Finished (covered; limited observations) ☐ Good condition ☐ Fair condition
- ☐ Unfinished/exposed soil ☐ Raised wood(limited observations) ☐ Removal of raised wood sub-floor is recommended.
- ☒

**FLOOR JOISTS/FLOOR SYSTEM****Type (floor & ceiling joists where visible)**

- ☒ Wood joists ☐ Wood Trusses ☐ Steel joists/concrete deck ☐ EWP ☐

**Floor system appears to be in:** ☒ Good condition where visible ☐ Fair condition where visible☐ Some localized repairs/ defects ☐ Repair/ replace floor joists at: **BASEMENT WINDOWS/VENTILATION & INSULATION**

- ☒ Good ventilation ☐ Fair natural ventilation supplied to basement/ crawlspace. ☐ None
- ☐ Replacement/ upgrade of all/ some basement windows are recommended. ☐
- ☐ Supply ventilation to:  ☐ Weather strip cold storage room door.
- ☐ Insulation recommended at:  ☐ Replace door to cold storage room.

**WATER SEEPAGE/PENETRATION (visible condition only with use of moisture meter)****NOTE: A mold/IAQ inspection is recommended in the event of active water leaks/dampness or high humidity levels.**

- ☒ No visual evidence of active water penetration through foundation walls. ☐ ? (limitations of visual inspection are in effect)
- ☐ Dampness/ efflorescence noted on foundation walls. ☐ Dampness/ moisture observed at cold storage room.
- ☐ Active leaking/seeping observed through foundation walls at:
- ☐
- ☐ Possible major damage to interior finishes as result of ongoing/ previous leaks and moisture. Further review recommended.
- ☒ Previous leaking/ **seeping** which measured dry observed through foundation walls at:
- ☐ All areas of foundation walls not thoroughly inspected due to finished wall coverings and storage of material/etc.
- ☒ See Additional Comment Page

**FOUNDATIONS BASEMENTS & STRUCTURES COMMENT PAGE**

Most of the foundation was is covered and not visible

The floor of the addition has signs of seepage or discolouration but was dry at the time of inspection.

Most of the ceiling of the basement is covered- Where visible the floor joist appear to be in good condition.

There is a small concrete lined pit in the basement flook adjacent to the furnace. At the bottom there is what appears to be  
clean out cover for the sewage drain- Have a plumber confirm.

The condensate line from the furnace and the humidefier discharge line empty into this pit and seeps into the soil through bottom of the pit.

It is recommended that these lines terminate in a floor drain.

**ELECTRICAL SYSTEM**

Major Repair  
Minor Repair  
N/A  
Monitor  
Functional

**LIMITATIONS:**

- ☐ Ratio/ percentage of different wiring types are minimums (if provided). Further review by a licensed electrician is required.
- We cannot detect existence of knob & tube wiring behind walls and within junction boxes/outlet boxes.
- ☐ Access to main panel is restricted. Could not visually access or open main panel.
- ☐ Auxiliary systems not inspected: back-up generators, solar & battery power, low-voltage lighting, pool and spa systems.

☒ ☐ ☐ ☐ ☐

**MAIN ELECTRICAL STATION**

**Main disconnect rating:** ☐ 60A ☒ 100A ☐ 125A ☐ 200A ☐ 400A ☐  A

**Main panel service rating:** ☒ 60A ☒ 100A ☐ 125A ☐ 200A ☐ 400A ☐  A

**Main power disconnect type:** ☐ Circuit breaker ☒ Knife switch/cartridge fuse

**Supply voltage:** ☐ 120V ☒ 120V/240V ☐ 347V/600V **Service entrance conductors:** ☒ Cu ☐ Al ☐ Not visible

**Grounding conductor:** ☒ Good condition ☐ Not Determined ☐ Requires repair/replacement

**Location of main and distribution panels:** ☒ Basement ☐ Garage ☐ Attic ☐ Shed ☐

**Location of auxiliary distribution panels:** ☐ Basement ☐ Garage ☐ Attic ☐ Shed ☐

**Condition of main/auxiliary panels:** ☒ Good condition ☐ Fair condition

☐

Adequate sized main distribution panel is installed. ☐ Labelling of branch circuit panels is recommended.

Adequate number of circuits are available to properly distribute intended load. ☐

distribution panel(s) are recommended(for future use). ☐

☒ Spare circuits available at distribution panel:  Yes ☐ No spare circuits are available. Auxiliary panel is recommended.

☐ Double tapping noted at some circuits  Possible overloaded circuit situation. Monitor.

☒ ☐ ☐ ☒ ☐

**DISTRIBUTION Note: Determining branch wiring types is limited to visual inspection only.****Predominant visible branch wiring type:**

☐ Knob & tube (old copper)  % ☐ ? ☐ Romex (conventional copper)  % ☐ ?

☐ BX (metallic sheathed)  % ☐ ? ☐ Aluminum  % ☐ ? ☒ Ungrounded older romex 75 % ☒ ?

☐ **Note:** Aluminum wiring is the original/principal branch wire type. ☐ No unsafe conditions identified with outlets tested.

**BRANCH CIRCUITS OVERCURRENT PROTECTION:**

**At main distribution panel(s):** ☐ Glass fuses ☐ Cartridge fuses ☒ Breakers ☐

**At auxiliary panel(s):** ☐ Glass fuses ☐ Cartridge fuses ☐ Breakers ☐

**Fuses/breakers**

☒ Properly sized fuses/ breakers are presently used to protect branch circuits. ☐

☒ Arc fault circuit interrupters (A.F.C.I.) are recommended to be installed at panel to protect bedrooms/convenience receptacles.

☒ ☐ ☐ ☐ ☐

**General**

Good lighting source is provided to all habitable areas & service rooms.

☐ Additional lighting recommended at:

Good number of receptacles is provided to all habitable areas & service rooms.

☐ Additional receptacles recommended at:

☒ ☐ ☐ ☐ ☐

**REPAIR/UPGRADING RECOMMENDATIONS**

**Upgrade amperage of main service to:** ☐ 100 AMPS ☐ 200 AMPS presently or upon the next home improvement undertaken.

☒ **Most/** some convenience receptacles in dwelling do not have secondary ground (i.e. 2 prong); add GFCI receptacles.

**Rework poor wiring connections at:** ☒ Basement ☐ Garage ☐ Attic ☐ Panel ☐

☒ Repair/ replace lighting fixtures/ switches/ ceiling fans at:  See comment

☐

☐ Repair/ replace receptacles at

☐ Missing coverplates/ loose outlets/ exposed cabling observed at:

☒ Installation/ **maintenance** of smoke/CO alarms at all floor levels of the building/dwelling is required. ☒ A.F.C.I. **recommended/** bedrooms.

☒ G.F.C.I. receptacles are req'd at: ☐ kitchen counter ☒ exterior ☐ garage/ outbuilding ☒ bathrooms ☐ spa/ whirlpool bath

☐

☒ See Additional Comment Page

There are numerous light fixtures in the basement that connected with extension cord wiring. Some of the branch wiring

It is recommended to upgrade the total system if a major renovation is planned.



Major Repair  
Minor Repair  
N/A  
Monitor  
Functional

**LIMITATIONS**

- ☒ Determining winter comfort with specific areas is beyond the scope of a visual inspection.
- ☒ The heat exchanger is concealed within the furnace and cannot be reviewed.
- ☐ The outdoor temperature was too high to sufficiently review the heating system/ductwork and winter comfort.

**GENERAL COMMENTS**

**Energy source:** ☐ Oil ☒ Gas ☐ Electric **B.T.U rating**

**Furnace type:** ☐ conventional warm air furnace ☐ mid-efficiency warm air furnace ☒ high-efficiency warm air furnace

☐ HWT/Combo system ☐ Commercial roof top unit ☐ Ground source heat pump ☐ Fan/coil unit

☒ Approximate age of furnace 1 =  years. ☐ Approximate age of furnace 2 =  years.

**Probability of furnace 1 replacement within the next**  years ☐ high ☒ Medium ☐ Low ☐ ?

**Probability of furnace 2 replacement within the next**  years ☐ high ☐ Medium ☐ Low ☐ ?

**Chimney flue interior:** ☐ Clay lined ☐ Metal lined ☐ Brick lined ☒ Direct vent ☐ Metal lining of flue required.

**Furnace room ventilation:** ☒ Good ☐ Fair

**Thermostat condition:** ☒ Good ☐ Requires replacement **Thermostat location:** ☒ Good ☐ Requires relocation

**Heat source supplied to habitable areas/zones**

**Basement:** ☒ Yes ☐ No **Main floor:** ☒ Yes ☐ No **2nd floor:** ☒ Yes ☐ No **3rd floor:** ☒ Yes ☐ No

Habitable room(s) not provided with a heat source:

**WARM AIR SYSTEM-FURNACE** ☐ Good overall condition ☒ Fair overall condition ☐ CO emission test required.

Drive/motor operation: ☐ Good ☒ Fair ☐ Requires repair/ replacement

Clean air/filtration system: ☐ Good ☐ Fair ☐ Requires repair/ replacement/ upgrade

Central humidifier operation: ☐ Good ☒ Fair ☐ Requires repair/ replacement/ removal/ upgrade

Burner(s)/coil condition: ☐ Good ☒ Fair ☐ Requires repair/ replacement

Limit and operating controls ☐ Good ☒ Fair ☐ Requires repair/ replacement

Venting condition: ☐ Good ☒ Fair ☐ Requires repair/ replacement

☒ Annual servicing and cleaning recommended. ☒ Heating company insurance plan recommended. ☒ Air duct cleaning is recommended.

☐ Carbon monoxide (CO) detector is required.(all levels) ☒ TSSA inspection tag missing.  Further review required.

**DISTRIBUTION SYSTEM - AIR DUCT SYSTEM**

Condition of supply plenum: ☐ Good ☒ Fair ☐ Requires repair

Condition of return plenum: ☐ Good ☒ Fair ☐ Requires repair

Condition of branch ducts: ☐ Good ☒ Fair ☐ Requires repair

Condition of register/grilles: ☐ Good ☒ Fair ☐ Requires repair

Condition of return ducts/inlets: ☐ Good ☒ Fair ☐ Requires repair

Air flow at supply outlets: ☐ Good ☒ Fair ☐ Requires repair

**HEATING FUEL STORAGE DISTRIBUTION SYSTEMS**

☒ Location of gas shut off/ **gas meter**/oil tank valve:  ☐ Approximate age of oil tank

☒ Good condition ☐ Paint exterior gas piping ☐ Requires repair/ replacement

**SUPPLEMENTARY HEATING** (Cannot substantiate effectiveness of in-floor heating due to the limitations of a visual inspection)

☐ Electric heaters/ space heaters/ in-floor heat have been installed at the following areas:

☐ Supplementary heating is recommended at the following areas:

☐ Rooms above unheated space:  garages:  crawlspaces:

**NOTE:** These rooms may be slightly cooler than other areas of the house during cold winter days.

☒

☐ See Additional Comment Page

## CENTRAL AIR CONDITIONING SYSTEM

Major Repair  
Minor Repair  
N/A  
Monitor  
Functional

## LIMITATIONS

- ☒ Due to the unpredictable nature of air conditioner failures no opinion can be given to system life expectancy or future performance.
- ☒ Data plate was missing/ **not legible**; limited inspection. ☐ Winterized/covered could not review.
- ☐ Solariums/ skylight vaults/ lofts/3rd floor levels are difficult to cool. Supplementary cooling may be required.
- ☒ The outdoor temperature was too low to safely activate the air conditioning system. Review prior to transaction closing

## GENERAL INFORMATION

**Energy source:** ☒ Electric ☐ Gas ☐ Combination system

**System type:** ☒ Split system ☐ Integral system ☐ Heat pump ☐ Condominium supply/fan coil unit

**Type:** ☒ Air to Air ☐ Ground source ☐ Ductless system ☐ Roof mounted ☐ Interior water cooled

Approximate estimated cooling capacity of system #1  B.T.U.'s or  2  tons ☒ ?

Approximate age of cooling system #1  25+ ☒ ? ☐

Approximate estimated cooling capacity of system #2  B.T.U.'s or  tons ☐ ?

Approximate age of cooling system #2  ☐ ? ☐

## EXTERIOR EQUIPMENT (FOR SPLIT SYSTEMS ONLY)

Clear of shrubs or plant growth: ☒ Yes ☐ No Unit properly mounted(level) on solid base. ☐ Yes ☐ No

Unit properly positioned out of direct sunlight: ☒ Yes ☐ No ☐

Electrical connections satisfactory: ☒ Yes ☐ No ☐

Condition of condenser fins: ☐ Good ☒ Fair ☐ Cleaning required

Condition of insulation of low-pressure refrigerant line (where visibly accessible): ☐ Good ☒ Fair ☐ Repair required

☐

## INTERIOR EQUIPMENT

Condition (operation) of condensate line: ☐ Good ☒ Fair ☐

Condition of refrigerant lines: ☐ Good ☒ Fair ☐

**Thermostat condition:** ☒ Good condition ☐ Requires replacement

**Thermostat location:** ☒ Good location ☐ Requires relocation

## INDEPENDENT SYSTEMS/ATTIC MOUNTED UNITS

Equipment in well ventilated area: ☐ Yes ☐ No ☐

Condition/operation of blower coil: ☐ Good ☐ Fair ☐

Proper condensate drain connection: ☐ Yes ☐ No ☐

Air duct connections at main unit: ☐ Good ☐ Fair ☐

Air filter condition: ☐ Good ☐ Fair ☐ Cleaning/replacement required

## COOLING DISTRIBUTION SYSTEM

☒ Using existing heat ducts (see heat distribution system). ☐ Using separate air duct system

Condition of air duct system: ☐ Good condition ☒ Fair condition ☐ Seasonal duct balancing required.

☐

## Cooling source supplied to habitable areas/room of:

**Basement** ☒ Yes ☐ No **Main floor** ☒ Yes ☐ No **2nd floor** ☒ Yes ☐ No **3rd floor** ☒ Yes ☐ No

☐ Rooms with no cooling outlet:

## Functional return-air system on each habitable floor level:

**Basement** ☐ Yes ☒ No **Main floor** ☒ Yes ☐ No **2nd floor** ☐ Yes ☒ No **3rd floor** ☐ Yes ☒ No

☐ Return-air system is recommended at 2nd/ 3rd level to optimize air flow.

## GENERAL CONDITIONS

- ☐ System was operating normally at the time of inspection. ☒ Check operation of AC prior to transaction closing.
- ☐ System is functioning abnormally; further analysis is required.
- ☐ Manufacturers' warranties appear to have expired on major components; system is in fair overall condition.
- ☒ System/major components are approaching end of expected functional life. Budget for replacement.
- ☐ See Additional Comment Page

**INTERIOR PLUMBING SYSTEM**

Major Repair  
Minor Repair  
N/A  
Monitor  
Functional

**LIMITATIONS**

- ☒ Visual access to main drain and drains underneath basement floors is restricted. No assurances can be provided regarding proper drainage conditions or performance. Sewer back-up is beyond our ability to detect or predict. ☐ Camera inspection recommended.
- ☐ We are unable to detect/ predict slow leaks in drains and water lines.

**WATER SUPPLY:** ☒ Municipal ☐ Private **SEWAGE DISPOSAL:** ☒ Municipal ☐ Private ☐ ?

**MAIN SHUT-OFF VALVE/LEVER**

**Location:** ☒ Basement ☐ Front wall ☐ Location not determined

☒ Good condition ☐ Fair condition ☐ ? ☐ Requires repair/ replacement

**TYPES AND VISIBLE CONDITIONS OF WATER SUPPLY LINES (limitations in effect)**

**Predominant type:** ☒ Copper piping ☐ Galvanized steel ☐ ? ☐ PEX ☐

**Visible condition:** ☒ Good condition ☐ Fair condition ☐

☐

☐ Removal of all galvanized water lines is required to increase water flow and pressure to a desirable level.

**Water pressure:** ☐ Good water pressure ☒ Fair water pressure ☐ Poor water pressure

**Functional flow:**

☐ Good functional flow to 2 fixtures when used simultaneously. Basement fixtures excluded.

☒ Fair functional flow is evident ☐ Poor functional flow is evident ☐ Upgrade of main water service is recommended.

**TYPES AND VISIBLE CONDITIONS OF INTERIOR WASTE/DRAIN LINES**

**Predominant type:** ☒ Cast iron/lead ☒ Copper piping ☒ ABS/plastic ☐ Galvanized steel

**Visible condition:** ☒ Good condition ☐ Fair condition ☐

☒ No abnormal drainage conditions were observed with all fixtures.

☐ Repairs required to vent stacks at:

☐ Replace main cast iron stacks and soil lines upon next renovation to house.

☐ Repairs required to main drain lines at:

☐ Clogged slow draining fixtures at:

☐ Improperly installed fixture drains at:

☐ Leaking fixture drains at:

☒ Fixtures with fair functional drainage that appear to be improperly vented: ☐ Basement toilet

☐

**BASEMENT/CRAWLSPACE FLOOR DRAIN (visible conditions)**

☐ Good condition ☐ Fair condition ☒ Requires repair/ replacement/ **cleaning** ☒ Back water valve recommended

☐ Location not determined ☐ Floor drain not installed ☐

**HOT WATER TANK** ☐ Rental ☐ Owned ☐ ? ☐

**Energy source:** ☐ Gas ☐ Oil ☐ Electric **Type:** ☒ Tank ☐ Tankless ☐ Combination

Hot water tank is in: ☒ Good condition ☐ Fair condition ☐ Requires repair/ replacement ☐ Old; replace

Venting condition (gas/oil only): ☐ Good/ fair condition ☐ Metal lining recommended ☐

**SUMP PUMP/SEWAGE EJECTOR SYSTEMS** ☐ Could not test/sump dry/inaccessible/too cold outside

**Condition of sump:** ☐ Good ☐ Fair condition ☐ Requires repair/ replacement

**Operation of pump:** ☐ Good ☐ Fair condition ☐ Requires repair/ replacement

**Condition of pump discharge:** ☐ Good ☐ Fair condition ☐ Requires repair/ replacement ☐ Add cover to sump pump

**PRIVATE WATER SOURCE** ☐ NOTE: Limitations of visual inspection is in effect.

**Type:** ☐ Pond/stream/spring ☐ Well ☐ Vault/cistern **Location** ☐

**Operation of pressure tank:** ☐ Good ☐ Fair condition ☐ Requires repair/ replacement

**Operation of (well) pump:** ☐ Good ☐ Fair condition ☐ Requires repair/ replacement

**PRIVATE SEWAGE DISPOSAL SYSTEM** ☐ NOTE: Limitations of visual inspection is in effect.

**Type:** ☐ Septic system ☐ Holding tank ☐ Not determined **Location:** ☐

Percolation field free of trees/shrubs: ☐ Yes ☐ No ☐ Not determined **Location:** ☐

☐ See Additional Comment Page

## GENERAL INTERIOR ELEMENTS

Major Repair  
Minor Repair  
N/A  
Monitor  
Functional

## LIMITATIONS:

- ☒ We are unable to detect or predict damage to interior finishes as result of slow or intermittent water leaks. Mold detection/indentification and/or analysis is beyond the scope of a visual inspection. Thermal seal failures of thermalpane glass is beyond our ability to detect or predict.

## WALL &amp; CEILINGS

**Predominant material type:** ☐ Plaster & wood lath ☐ Plaster & gypsum lath ☒ Drywall ☐ Wood/paneling

**General condition of surfaces:** ☐ Good condition ☒ Fair condition ☐ Substantial refurbishing recommended/ paint.

☐ Most/ some ceilings/ walls are aged; drywalling over existing surfaces is recommended in the near future.

☐ Repair required at:

**Wall structure type:** ☒ Wood ☐ Steel ☐ Masonry & strapping **Alternate ceiling type:** ☐ Suspended/ acoustic tile

☐ Water stains noted at [rd floor rear room- beside light moisture noted on ceiling surfaces](#) which were measured dry. Monitoring required.

## FLOOR COVERINGS

**Predominant material type:** ☐ Carpet ☒ Hardwood ☐ Wood ☒ Vinyl ☐ Laminate ☐ Tile/Stone

**General condition of surfaces:** ☐ No hazardous defects exist(normal wear) ☐ Substantial refurbishing recommended

☐ Repair required at:

☐ 2nd/ 3rd level floor system was not originally intended for habitable use and is presently limited in its ability to support a normal load.

☒ [2nd floor - rear room- floor tiles may contain asbestos.](#)

## PRIMARY WINDOW OPERATION/CONDITION

## Function of ventilating windows

☐ Good condition ☒ Fair condition ☐ Minor adjustment most/ some units

☐ Major refurbishing/ replacement is recommended:

## Window glazing/panes:

☒ Thermal windows with highly visible defective [seals/ condensed](#) panes at: [Throughout](#)

☒ Various cracked glass panes are noted. ☐ Most/ some panes are single glass only; improvement recommended

## Window handles/locks/hardware:

☐ Good condition ☒ Fair condition ☐ Some localized repair/ upgrading/ missing

☐ All/most operating windows have insect screens. ☐ Few/ most insect screens are required to be repaired/ installed

## PRIMARY DOOR OPERATION/CONDITION

## Function of interior doors:

☐ Good condition ☒ Fair condition ☐ Minor refitting to most/ some doors

## Door hardware-general conditions:

☐ Good condition ☒ Fair condition ☐ A few missing handles/ repairs required ☐ Most require improvement

## STAIRWAYS/RAILINGS &amp; BALCONIES

**Condition of primary staircase(s):** ☐ Limited headroom and/ or clearances.

☐ Good condition ☒ Fair condition ☐ Loose treads/ minor repair ☐ Major repair/ replacement recommended

## Condition of primary railings/guards:

☐ Good condition ☒ Fair condition ☐ Loose rails/ spindles/ minor repair

☐ Installation of safety handrail recommended/ upper flight only ☐ Guardrails too low/ spindle spacing unsafe/ missing

**Condition of basement staircase(s):** ☐ Limited headroom/ clearances.

☒ Good condition ☒ Fair condition ☐ Loose treads/ minor repair ☐ Major repair/ replacement recommended

## Condition of basement railings/guards:

☐ Good condition ☒ Fair condition ☐ Loose rails/ spindles/ minor repair

☐ Installation of safety handrail recommended/ upper flight only ☐ Guardrails too low/ spindle spacing unsafe/ missing

**Condition of 3rd floor/supplementary staircase(s):** ☐ Limited headroom/ clearances.

☐ Good condition ☒ Fair condition ☐ Loose treads/ minor repair ☐ Major repair/replacement recommended

## Condition of 3rd floor/supplementary railings/guards:

☐ Good condition ☒ Fair condition ☐ Loose rails/ spindles/ minor repair

☐ Installation of safety handrail recommended/ upper flight only ☐ Guardrails too low/ spindle spacing unsafe/ missing

☐ See Additional Comment Page

**ATTIC/ROOF SPACES**

Major Repair  
Minor Repair  
N/A  
Monitor  
Functional

**LIMITATIONS:**

- ☒ The inspection process cannot predict the ability of the roof structure to support heavy snow loads.
- ☐ Could not access attic due to seized cover/ no attic access/ further review is required prior to proceeding.
- ☐ Attic reviewed at hatch access. Floor not walked on. All attic spaces were not fully inspected.

**ACCESSIBILITY**

- ☐ Good/ fair access to attic ☐ Attic floor walked on ☐ Attic has lofting potential
- ☐ Attic roof space has been converted into living space ☐ Attic interconnected with adjacent dwelling. Install firewall/fire separation.
- ☐ No access to attic is installed ☐ Access not required ☐ Access to roof spaces/ knee wall spaces is recommended.
- ☐ Relocate access ☐ Increase size of attic access ☐ Insulate/ weatherstrip hatch ☐ Additional access required.

**VENTILATION**

- ☐ Domed roof units ☐ Soffit vents ☐ Gable/ ridge vents ☐ Attic fan(s)/ turbine vents ☐ Spaced board sheathing

**Roof vent(s):** ☐ Good condition ☐ Fair condition ☐ Repair/ replace roof vents at:

- ☐ Additional vents recommended at soffit/ ridge area ☐ Soffit baffles to be installed in the attic at eaves section.

**INSULATION**

**Approx. R-value:** ☐ R0 to R15 (0-5) ☐ R20 to R28 (6-8) ☐ R32 to R40 (10-12) ☐ R40+

**Type:** ☐ Cellulose fibre ☐ Fibre glass batts/ loose fill ☐ Rock wool ☐ Vermiculite ☐

- ☐ Additional insulation recommended to be installed on the attic floor. ☐ Additional insulation recommended around air ducts.

- ☐ Insulation is unevenly distributed on attic floor. Add/ redistribute insulation.

**Evidence of vapor retarders:**

**ROOF STRUCTURES (where visible)**

**Type:** ☐ Rafters/ Collar ties ☐ Trusses ☐ Good condition ☐ Fair condition ☐ Some localized repairs/ defects

- ☐ Additional collar ties/ structural support is recommended.

**ROOF BOARDS/SHEATHING (where visible)**

**Type:** ☐ Plywood ☐ Board sheathing ☐ Good condition ☐ Fair condition

- ☐ Probability of replacement of some/ most sheathing with next shingle replacement

- ☐ Fair/ poor condition due to inadequate ventilation. Possible mold/ mildew residue developing on sheathing.

- ☐

- ☐ See Additional Comment Page

**KITCHEN****COUNTER TOP CONDITION**

Counter top is in: ☐ Good condition ☒ Fair condition ☐ Requires repair/ replacement

- ☐ Localized damage around faucets; counter replacement is imminent.

**CABINET(S) CONDITION**

Cabinet condition installation & operation is in ☐ Good condition ☒ Fair condition

- ☐ Repairs required to drawers/ door fronts/ shelving/ cabinet mounting.

**STOVE POWER SOURCE**

- ☒ Plug receptacle installed/240V ☐ Direct wire connection/no receptacle ☐ Gas stove connection ☐ T.S.S.A tag required ☐ Not visible

**EXTRACTION FAN**

Exhaust fan is in ☐ Good condition ☐ Fair condition ☐ Repair/ replace fan ☒ Installation of exhaust fan recommended

- ☒ Re-circulating fan is functional ☐ Fan is not vented to exterior

**ELECTRICAL RECEPTACLES**

- ☒ Good/ fair number of receptacles installed at counter level ☐ Ungrounded receptacles(s) in kitchen noted

- ☐ Limited number of receptacles in kitchen ☐ Additional split duplex receptacles recommended

**SINK/FAUCET CONDITION**

Sink is in: ☒ Good condition ☒ Fair condition ☐ Sink requires repair/ replacement

Faucet assembly is in ☐ Good condition ☒ Fair condition ☐ Requires repair/ replacement/ new washers/ cartridge

- ☐ Garborator is in function condition ☐ Repair/ replace garborator

- ☐

**GENERAL CONDITIONS**

The  kitchen is in marginal condition. Major remodelling is recommended in the near future.

- ☐ See Additional Comment Page

**BATHROOMS**

Major Repair  
Minor Repair  
N/A  
Monitor  
Functional

☒ ☐ ☐ ☐ ☐

**LIMITATIONS**

☒ Due to the unpredictable and latent nature of plumbing shower and bathtub enclosure leaks there can be no assurances or warranty that leaks will not develop at any time after the inspection date. The development of mold is a common result of leaks in the bathroom. We cannot predict or detect damage behind walls.

**SHOWER/BATHTUB ENCLOSURE CONDITION**

- ☐ The ceramic tile/ wall surfaces are in good general condition. ☒ The ceramic tile/ wall surfaces are in fair general condition.
- ☒ Sealant and grout touch-ups/ repair required at all/ most shower/ bathtub enclosures.
- ☐ Shower enclosure exhibits no evidence of leaking but is at the end of expected lifespan at:
- ☐ Repair/ replace tile or wall surface at:
- ☐ Complete tile and wall replacement required at:
- ☐ Repair/ install shower door/ curtain assembly at:

☒ ☐ ☐ ☐ ☐

**FAUCETS/SHOWER HEAD CONDITION**

- ☒ Shower faucets/ head assembly are in good/ fair general condition ☐
- ☐ Tub faucets are in good/ fair general condition ☐ Faucets washers/ cartridge are to be replaced.
- ☐ Shower faucets/ head assembly requires repair/ replacement at:
- ☐ Tub faucet requires repair/ replacement at:

☒ ☐ ☐ ☐ ☐

**BATHTUB CONDITION**

- ☒ Bathtubs are in good/ fair general condition ☐ Reglazing/re-lining of bathtub recommended at:
- ☐ Bathtubs requires repair/ replacement at:
- ☐ Whirlpool bath is functional ☐ Whirlpool bath requires repair at:
- ☐ Whirlpool bath electrical circuit is required to be protected by an accessible GFCI breaker.
- ☐ No access panel/ improper access to mechanical equipment at:

☒ ☐ ☐ ☐ ☐

**TOILET CONDITION/BIDET CONDITION**

- ☒ Toilets are in good/ fair general condition ☐ Toilet requires repair/ replacement at:
- ☐ Toilet is improperly installed to floor (ie) loose at:
- ☐ Bidet in good/ fair general condition ☐ Bidet requires repair at:

☒ ☐ ☐ ☐ ☐

**WASH BASINS/FAUCET CONDITION & OPERATION**

- ☒ Wash basin are in good/ fair general condition. ☐
- ☐ Wash basin requires repair/ replacement at:
- ☐ Faucets are in good/ fair general condition. ☐ Faucet washers/ cartridge are to be replaced.
- ☐ Faucets require repair/ replace at:

☒ ☐ ☐ ☒ ☐

**ELECTRICAL**

- ☐ Receptacles are in functional condition at all/ most bathrooms ☐ None installed.
- ☐ Installation of GFCI receptacle recommended at:
- ☐ Repair/ replace receptacle at:  ☐ Ungrounded receptacle at:
- ☐ Repair/ relocate light fixture at:

☒ ☐ ☐ ☐ ☐

**VENTILATION: WINDOWS/EXHAUST FANS**

- ☒ Ventilation is provided by a functional window and/or a functional mechanical exhaust fan.
- ☐ Repair/ replace exhaust fan at:
- ☐ Fan not vented to exterior at:  ☐ Could not determine
- ☐ Exhaust fan installation recommended at:
- ☐ Rework window to provide proper operation/ replace window at
- ☐ Window is located in shower enclosure; protection of window is required at:

☐ ☐ ☒ ☐ ☐

**SAUNAS/SPAS/STEAMER**

- ☐ Sauna/ steamer/ hot tub are in good/ fair general condition. ☐
- ☐ System/ components require repair/ replacement at:

☐ ☐ ☐ ☐ ☐

**GENERAL CONDITIONS**

The  bathroom is in marginal condition. Major remodelling is recommended in the near future.

☐ See Additional Comment Page



**FIREPLACES**

Major Repair  
Minor Repair  
N/A  
Monitor  
Functional

**LIMITATIONS:**

☐ Inspecting condition of flue and ability of fireplace to draw is beyond scope of visual inspection. Camera inspection of flue is rec'd.

**FIREPLACE TYPE**

Masonry fireplace at:

Wood-burning stove at:

Factory-built fireplace at:

Wood/ coal insert at:

Gas fireplace at:  ☐ TSSA inspection tag missing. Further review required.

☐ ☐ ☒ ☐ ☐

**FIREPLACE CONDITION**

☐ Combustion chamber is in good/ fair condition. ☐ Damper is in good/ fair condition.

☐ Hearth extension is in good/ fair general condition ☐ Smoke chamber is in good/ fair general condition.

☐ Combustion chamber requires repair at:

☐ Damper requires repair/ replacement at:

☐ Hearth floor requires repair/ extending at:

☐ Smoke chamber requires repair at:

☐ Note: Basement fireplace may not draw properly. ☐ Alternative repair/ improvement strategy recommended

☐ Flue cleaning recommended at:  ☐ Service/ clean/ repair gas fireplace(s)

☐ Roughed-in fireplace installed at:  ☐ Fireplace is obsolete/ disconnected at:

☐ ☐ ☒ ☐ ☐

**Non-combustible base/lateral clearances from combustible materials of wood burning stoves.**

☐ Good condition ☐ Fair condition ☐ W.E.T.T inspection/ camera inspection of flue recommended.

☐ Improvement required at:  ☐ Stainless steel liner recommend at:

☐ Do not use  fireplace until certified as safe.

☐ See Additional Comment Page

**LAUNDRY ROOM**

☐ ☐ ☒ ☐ ☐

**CLOTHES DRYER CONNECTIONS**

**Power source:** ☒ Plug receptacle 240 V ☐ Direct wire; no plug ☐ No electrical connections ☐ Gas dryer connection ☐ Not visible

**Dryer venting:** ☒ Properly vented to the exterior. ☐ Duct/ vent requires repair/ cleaning/ repair at exterior ☐ No venting installed

☐ Replace with metal duct. ☐ Vented through window; rework. ☐

☒ ☐ ☐ ☐ ☐

**WASHING MACHINE CONNECTIONS**

**Power source:** ☒ Plug receptacle available & properly grounded. ☐ No plug receptacle installed/replace receptacle.

**Water connections:** ☒ Satisfactory connections/ shut off valve. ☐

☐ Connections require repair/ replacement/ relocating. ☐ Replace connection hoses with steel braided lines

☒ ☐ ☐ ☐ ☐

**LAUNDRY TUB/FAUCETS** ☐ None: Installation recommended

Tub is in: ☐ Good condition ☒ Fair condition ☐ Tub requires repair/ replacement

Faucet is in: ☐ Good condition ☒ Fair condition ☐ Faucet requires repair/ replacement ☐ New washers required

☐ ☐ ☒ ☐ ☐

**EJECTOR PUMP FOR LAUNDRY TUB** ☐ Good condition ☐ Fair condition ☐ Pump requires repair/ replacement

**FURTHER INQUIRIES TO SELLER OF PROPERTY**

☐ Ask seller for any manufacturer's warranties or service contracts for appliances and equipment and recent home improvements.

☐ Ask seller for plans/drawings/project documentation and permits for any improvements to the property.

☐ Ask seller for list of tradespeople and service technicians who have worked on the property.

☐ Inquire to seller about cause of water stain on  ceiling/ wall.

☐


☐

☐ See Additional Comment Page

## Interior Image



Moisture detected in the area where the flat ceiling meet the sloped surface



Thermal image showing location of moisture