### **20/20 HOME INSPECTIONS**

40 Stockell Crescent

Ajax, Ontario L1T 0M4

Telephone: 416-518-9680

# HOME INSPECTION REPORT



Property Address: 73 McMurray Ave Date of inspection: October 6th 2020

## **Prepared By:**

Pradeep Samaroo, RHI

#### **20/20HOMEINSPECTIONS**

40 Stockell Crescent Ajax, Ontario L1T 0M4 T: 416-518-9680 E: pradeep\_samaroo@hotmail.com W: www.2020homeinspections.ca

**Our Vision is Your Peace of Mind** 

Residential and Commercial Property Inspections Buyers Home Inspections Inspections for Sellers Prior to Listing Thermal Imaging Inspections of Newly Constructed Homes

| 20/20HOMEINSPECTIONS   |  |
|--|--|
| 40 Stockell Crescent Ajax Ontario L1T 0M4  |  |
| Telephone: 416-518-9680 www.2020homeinspections.ca   | pradeep_samaroo@hotmail.com  |
| PRE-LIST SUMMARY   |  |
| Address: 73 McMurray Ave Municipality: Toronto 💌 Insp  | bection Date: October 6th 2020   |
| General Information: House was substantially updated approx 8 years ago                      | Inspector: Pradeep Samaroo, RHI  |
| Age of House 100 years. Construction Type: 2 storey 💌 row hou                                | ise vick veneer vice veneer veneer vice veneer venee |
| This house is in well above average velocities functional condition in comparison to other s | similar age and size homes in the neighbourhood.   |
| On average; a house of similar age/size and quality will cost you \$3500-\$4500 💌 for a      | nnual general repairs and on-going maintenance.  |
| You will require \$1000 (minimum) to address the fun   | ctional concerns listed in the the report over the next $0-1$  |
| MAJOR SYSTEMS - GENERAL DESCRIPTION AND CONDITIONS:  |  |
| Roofing systems: tar & gravel  Secondary roofing system: flat roof membra                    | ne 💌 💌   |
| Exterior wall systems: brick veneer 💌 Secondary wall siding: aluminur                        | n siding   |
| Windows(general): Updated: vinyl sliders/casements   |  |
| Electrical Systems   |  |
| Main service size 100 💌 amp circuit breakers 💌 Predominant branch v                          | viring: romex/copper   |
| Heating System   |  |
| Fuel type: natural gas 💌 Age of central heating appliance: 8 years                           | System type: high-efficiency forced air furnace  |
| Cooling System   |  |
| System type: central A/C-low velocity Age of cooling equipment: 8                            | years Approx. tons: 2 tons   |
| Plumbing System  |  |
| Main supply: 1/2 inch copper line Predominant water lines PEX                                | ▼  |
| Interior (general): most elements have been substantially upgraded                           |  |
| HOMEOWNER INSURANCE CONCERNS   |  |
| ✓ None Identified  |  |
|  |  |
| REQUIRED REPAIRS/MAJOR SYSTEMS AND COMPONENTS APPROACHING                                    | G END OF EXPECTED LIFE SPAN  |
|  | he frame vears Budget \$   |
| Correctly install Gas line bonding wire  | he frame 0-1 vears Budget \$ 200   |
|  | he frame 0-1 vears Budget \$ 50  |
|  |  |
|  | he frame years Budget \$   |
|  | he frame vears Budget \$   |
| Tin  | ne frame vears Budget \$   |
| Tin  | he frame vears Budget \$   |
| Tim  | he frame years Budget \$   |
| Tin  | he frame vears Budget \$   |
| OTHER RECOMMENDATIONS  |  |
|  | <b>T</b>   |
|  | <b>•</b>   |
|  | <b>v</b>   |
|  |  |
| ADDITIONAL INFORMATION REQUIRED  |  |
|  | •  |
|  | <b>v</b>   |
|  |  |
| SUMMARY  |  |

# This report should not be considered as a complete home and property inspection. The 20/20 Home Inspections report is prepared for the owner to provide general information about this property. The inspector is available by telephone to any interested party to answer questions about the house. Please read the full report prior to calling the inspector. We are also available to provide any prospective buyer general orientation; helpful maintenance tips and improvement consulting for a fee. This general review inspection is essential to compare your expectations, intended use and special needs with the realities of the house. Interested parties should be advised that; without this general review our obligation and liability can only remain with the seller.

|   | 20/2  | OHOMEINSPECTIONS   |                  |               |                                |                    |  |          |  |
|---|-------|--|------------------|---------------|--------------------------------|--------------------|--|----------|--|
|   | 40 S  | otockell Crescent Ajax   | Ontario L1       | T 0M4         |                                |                    |  |          |  |
|   | Tele  | ephone: 416-518-9680   |                  | www.202       | 0homeinspections.ca            | pradeep_sa         | amaroo@hotmail.com                                       |          |  |
|   | PRF   | ELIMINARY BUILDING   | INSPECTI         | ON REPOI      | RT                             |                    |  |          |  |
|   | Prop  | perty Inspected 73 McMurr  | ray Ave          |               |                                |                    | Municipality Toronto                                     | -        |  |
|   | Insp  | ection Date October 6th 20   | )20              |               | Time 1:00- 3:30                |                    | Inspector Pradeep Samaroo, RHI                           | -        |  |
|   | SUN   | MMARY (GENERAL CO  | MMENTS)          |               |                                |                    |  |          |  |
|   | In co | omparison to other homes of  | f similar vin    | tage in the v | ricinity the functional condi- | tion of this build | ding/dwelling is; above average.                         |          |  |
|   | Reco  | ommended improvements or   | r repairs to the | he building/  | dwelling have been address     | ed in the report.  |  |          |  |
|   | It is | suggested that the highlight   | ed concerns      | be consider   | ed priorities.                 |                    |  |          |  |
|   | Plea  | se be advised that failure   | to address c     | oncerns pr    | omptly may result in addi      | tional problems    | s and/or consequential damages.                          |          |  |
|   |       |  | MINOR            | MAJOR         |                                | MINOR              | MAJOR  |          |  |
|   |       |  | REPAIRS          | REPAIRS       |                                | REPAIRS            | S REPAIRS  |          |  |
|   | Roo   | fing   |                  |               | Structure                      |                    |  |          |  |
|   | Exte  | eriors   |                  |               | Electrical                     | <b>P</b>           |  |          |  |
|   | Inter | riors  |                  |               | Heat/Cool                      |                    |  |          |  |
|   |       | ntenance   | <b>*</b>         |               | Plumbing                       |                    |  |          |  |
|   |       |  |                  |               |                                |                    |  |          |  |
|   | Corr  | ments: House is in exceller  |                  |               |                                |                    |  |          |  |
|   |       | 1  |                  |               |                                |                    |  |          |  |
|   | 1)    |  | -                | -             |                                |                    | care. This consulting service is limited to the physical |          |  |
|   |       | evidence that was visually   | accessible at    | t the time of | the inspection. This report    | is not transferab  | ble to anyone other than the client as this report doe   | es       |  |
|   |       | not include the verbal infor   | mation impa      | arted by the  | inspector which is vital to f  | ully understand    | the service and contract.                                |          |  |
|   | 2)    | The required repairs to the building include but are not limited to what is reported herein due to the limitations and restrictive nature                  |                  |               |                                |                    |  |          |  |
| ç   |       | of the visual inspection. The client is hereby warned that not all deficiencies will be discovered. At best 80% of the first year repairs should           |                  |               |                                |                    |  |          |  |
| pyri  |       | be revealed; not 100%. Det   | termining the    | e presence o  | f mold, fungi and other inde   | oor air quality co | ontaminants are specifically not included.               |          |  |
| ght (   | 3)    | The inspector's role is prin   | cipally educ     | ational; to p | rovide you with a better und   | derstanding of th  | he building. We will not detect all problems.            |          |  |
| BC  | 4)    | The preliminary inspection   | is partially     | designed to   | reduce your risk of buying     | an older home. H   | However we cannot eliminate this risk.                   |          |  |
| G 20  |       |  |                  | -             |                                |                    | rther inspections by specialists are required.           |          |  |
| Copyright CBCG 2016 -                         | 5)    |  |                  | -             |                                |                    | nance and unforeseen repairs.                            |          |  |
|   | 6)    |  |                  |               | -                              | -                  | if the recommended repairs in this                       |          |  |
| nsec  | 0)    |  |                  |               |                                | -                  | -  |          |  |
| to I  |       | -  | -                |               | is especially the case in mat  | -                  | -  |          |  |
| rade  | 7)    | -  | -                |               |                                |                    | e only. Estimates are based on the                       |          |  |
| ep S  |       |  |                  | -             |                                |                    | curate cost estimates from contractors immediately       | <i>.</i> |  |
| ama   | 8)    | The preliminary inspection   | does not co      | ver code co   | mpliance issues set by gove    | rnments or other   | r regulatory authorities.                                |          |  |
| IOO 1   | 9)    | The preliminary inspection   | does not tak     | ke into accor | unt manufacturer's recalls a   | nd eligibility for | r mortgage insurance, building or homeowners ins         | urance   |  |
| until   | 10)   | The preliminary inspection   | process is c     | onducted in   | a fair and impartial manner    | . Accordingly th   | his report is not provided as an aid for negotiation     |          |  |
| Nov   |       | in a real estate transaction. We do not overstate or under value any issue to benefit any party.   |                  |               |                                |                    |  |          |  |
| icensed to Pradeep Samaroo until November 15, | 11)   | The purchaser is advised to ask the property owner if they are aware of any defects that would not normally be detected by a visual inspection.            |                  |               |                                |                    |  |          |  |
|   |       | The purchaser is advised to revisit the property before closing to verify that functional conditions remain unchanged or retain the inspector for this tas |                  |               |                                |                    |  |          |  |
| 5, 2020                                       | 12)   | The client hereby acknowle   | edges they a     | re contractu  | ally obliged to contact the in | nspector immedi    | iately to arrange a site visit at no                     |          |  |
| 20  |       |  |                  |               |                                |                    | nflicting opinion and prior to any corrective work.      |          |  |
|   | I ha  | -  |                  |               |                                | -                  | . I accept this report and supplements accordin          | g to     |  |
|   |       |  | -                |               | -                              | -                  | onal time and is not a guarantee of present or fu        | -        |  |
|   | cone  | ditions and is not an insura   | ance policy      | of any kind   | . I am aware that I can ret    | tain the inspect   | tor to re-evaluate the property prior to closing f       | or       |  |
|   | evid  | ence of new water leaks a  | nd/or items      | not previou   | sly inspected due to seaso     | nal limitations    | for an additional fee.                                   |          |  |

| Name of Client Christine Siemiernik/Brian Hartigan | (Bus.) | (Res.) 416 700 8620 |
|--|--------|---------------------|
| Current Address 73 McMurray Ave. Toronto           | Other  |                     |
| E-mail:  |        |                     |

#### GENERAL CONDITIONS/SPECIAL SITUATIONS & LIMITATIONS

| GENERAL CONDITIONS/SI                           | I ECIAL SITUATIONS & LIMITATIONS  |
|---|---|
| The primary purpose of the insp                 | pection and report is to educate the prospective purchaser/owner about the general condition of the building.   |
| Repair and cost effective impro                 | vement advice is provided to increase this understanding. It is not a contractual obligation nor is it possible for the   |
|   | I problems solely on the basis of a visual examination. 80% of first year repairs should be revealed: not 100%.   |
| DEFINITION OF TERMS US                          | SED IN THE PRELIMINARY INSPECTION REPORT:   |
| Functional                                      | (1) system was performing its' intended purpose at the time of the inspection, no significant loss of functionality   |
| Monitor and/or Maintenance                      | (1) item is marginal; will require future repair or replacement. Owner is advised to monitor.   |
|   | (2) preventative maintenance repairs are required by property owner.  |
| Minor Repair                                    | (1) minor repair is recommended; cost should not exceed \$3000.00 and/or repair is not urgent.  |
| Major Repair                                    | (1) major repair is recommended; cost will exceed \$3000.00. Obtain contractor's estimates immediately.   |
| Good Condition                                  | (1) no defects were discovered that should require repair within the first six months, no significant loss of functionality   |
|   | Note: Limitations of a visual inspection and visually accessible physical evidence are in effect.   |
| Fair Condition                                  | (1) system or component is performing its intended purpose; but due to its age can fail at any time.  |
| N/A   | (1) not applicable/not accessible/not inspected/not installed or does not pertain to the subject property.  |
| (?)   | (1) performance/future performance of system or component is unpredictable. Further review is required.   |
| The inspector's objective during                | the summary portion of the inspection is to discuss the significant aspects of their findings. There is no time limit   |
|   | my questions as you like to ensure we have addressed your concerns. The inspection process is a two-part system:  |
|   | . This report is not transferable to third parties as it will not clearly convey the information herein.  |
| WEATHER CONDITIONS                              | limited the system of the systemic memory of the systemic memory of the system of the |
|   | limited the extent of the exterior inspection. Roof/ grade/ walkway/ decks were snow covered.   |
| -   | as too low to safely test the air conditioning system(s)/distribution systems and summer comfort.   |
|   | as too high to sufficiently test the central heating system/distribution systems and winter comfort.  |
| -   |   |
| Weather conditions during in<br>INACCESSIBILITY | spection: Rainy Snow Clear Cloudy Windy Temperature 10C to 15C V  |
| Basement/Garage storage 1                       | limited access/ visibility. Excessive storage limited access to: all basement closets and storage areas   |
|   | bogress not fully visually inspected:   |
| Other specific limitations:                     |   |
| <ul> <li>Plumbing system winterized</li> </ul>  | d (not fully inspected)   |
|   | shed  |
| <b>c</b>  |   |
| RENOVATIONS/REMODEI                             | LLING ned in this report are based on the intent of the client that upgrades will be done to the following:   |
| Exterior Addition                               |   |
| GENERAL/ORIENTATION                             |   |
| ✓ For reference purposes the f                  | front of the building is facing: 🔲 north 🔄 south 🔲 east 🗹 west  |
| Seller has warranted the foll                   |   |
| Further inquiries to seller is                  |   |
| TYPE OF INSPECTION/TRA                          |   |
|   | Pre-sale inspection Newly built house inspection Post-purchase inspection   |
| Home owners inspection                          | Estate sale Power of sale Private sale Pre-lease/rental inspection Pre-offer inspection   |
| ATTENDANCE                                      |   |
| Buyer/client not present at i                   | nspection Client partially attended inspection Client fully attended inspection   |
| Also in attendance: Seller                      | ✓ Seller's agent  |
| EXCLUSIONS                                      |   |
|   | ools & related equipment is beyond the scope of our visual inspections.   |
| Exterior/common elements                        | are the responsibility of the the condominium corporations. Review particulars with legal counsel.  |
| Appliances/central vacuum                       | systems/trees/heat exchangers/flue interiors/outbuildings/security system/intercom/spas/wood destroying insects/vermin  |
|   |   |

and animals/underground storage tanks/sub-grade plumbing drains/environmental testing/UFFI/mold and other indoor air quality contaminants/ window air conditioners/asbestos containing material/septic tanks/wells/marine structures and other items not specifically mentioned in the report are not included within the scope of this inspection. We do not disassemble equipment/bore holes into walls/floors and ceilings/move furniture and boxes/lift up carpets.

## COST ALLOWANCES/TIME FRAMES AND SHORT TERM COURSE OF ACTION YOUR EXPECTATION LEVEL

We have included this summary to help you prepare and budget for future work. Please be cautioned that the following noted items represent the minimum amount of work that you will address in the future. Be aware that you may receive opinions from other tradespeople or knowledgeable parties that can vary drastically from our own. In this instance we require you to contact us immediately to seek clarification or request a site inspection at no further expense.

#### GENERAL CONDITION AT THE TIME OF THE PRELIMINARY INSPECTION

Image: The subject property requires less current repair consideration than the average house/building of similar vintage

The subject property requires an average amount of repair consideration compared with other houses/buildings of similar vintage.

The subject property requires more current repair consideration than the average house/building of similar vintage.

| The average annual repair/maintenance budget for a home/building of similar size and vintage is: \$3500-\$4500 <b>v</b> OUR MINIMUM BUDGET ALLOWANCE:  |                     |                            |                 |                     |              |  |
|--|---------------------|----------------------------|-----------------|---------------------|--------------|--|
| ✓ over the first 0 - 2 years   |                     |                            |                 |                     |              |  |
| To address the functional concerns listed below you must budget at the very least the following amount:         □ \$2000-\$5000       □ \$10000-\$15000       □ \$15000-\$20000       ☑ \$1000 |                     |                            |                 |                     |              |  |
| AREAS REQUIRI  | NG CONSIDERATION    |                            |                 |                     |              |  |
| Roofing Systems:   | Roof Coverings      | Eavestroughs/down pipes    | Overhangs       | Chimneys/flashings  | Skylights    |  |
| Exterior:  | Brick/sidings/walls | Windows/doors              | Site drainage   | Porches/decks       | Painting     |  |
|  | Garage/sheds        | Driveway/walkway           | Landscaping     | Fencing/gates       | ✓ Flashing   |  |
| Structures:  | Crawlspaces         | Beams/columns              | Floors          | Foundation wall     |              |  |
| Electrical Systems:  | Main service/panels | Lighting fixtures/switches | Branch wiring   | Receptacles/outlets | Bonding wire |  |
| Heat/Cool Systems:   | Furnace/boiler      | Distribution: ducts/rads   | AC system       | Filters/humidifiers |              |  |
| Plumbing Systems   | Main water service  | Distribution piping        | Drains/vents    | Fixtures/fittings   |              |  |
| <sup>1</sup> Interiors:  | Kitchen             | Basement spaces            | Bathrooms       | Attic/roof spaces   | Fireplaces   |  |
| ·<br>·   | Walls/ceilings      | Floor coverings            | Stairs/railings | Appliances          | Decorating   |  |

🗹 General annual & seasonal exterior/interior building maintenance & small repairs

#### YOUR RECOMMENDED COURSE OF IMMEDIATE ACTION:

Please review the preliminary report in its entirety and ask for clarification on any matter. This page must not be relied upon in isolation. Prior to continuing with the next step of the transaction/project consider the issues listed in the report. We advise you to consult with your realtor or lawyer regarding options on how to proceed. Also instruct your lawyer to obtain Title Insurance for you. You should request additional inspections as outlined in the full report to address your special concerns and/or matters that we can not inspect. You must also factor the limitations of the building inspection in your decision making process. 80% of first year repairs should be revealed: NOT 100%. Therefore you must anticipate and budget for the 20% unforeseen deficiencies that will not be discovered by a visual inspection. You must ask the seller for invoices/applicable warranties/plans and/or permits for work completed in the last five years. Consider all deficiencies related to health/ safety issues and uncontrolled water problems as urgent matters.

| See survey summary on preceding page for priorities and costs.     | •                   |                       |   |
|--|---------------------|-----------------------|---|
|  |                     |                       |   |
|  |                     |                       |   |
|  |                     |                       |   |
|  |                     |                       |   |
|  |                     |                       |   |
|  |                     |                       |   |
|  |                     |                       |   |
| Further clarification regarding:                                   |                     |                       |   |
| Termination of exhaust fans of the bsmnt washroom and laundry area | is required of the: | Property owner/vendor | ▼ |
|  | is required of the: |                       | ▼ |
| Further inspection/evaluation is required regarding:               |                     |                       |   |
|  |                     | <b>T</b>              |   |
|  |                     |                       |   |
|  |                     |                       |   |
|  |                     | •                     |   |
|  |                     |                       |   |

☑ OBTAIN CONTRACTORS QUOTES/REPAIR SPECIFICATIONS ON ANY MAJOR REPAIR NOTED HEREIN IMMEDIATELY.

| 1/2-Yr. Priority Ke  | y ROOF STRUCTURES COVERINGS & RELATED SYSTEMS  |
|--|--|
| Maj<br>Min<br>N/A<br>Mor                                     | METHOD OF ROOF INSPECTION  |
| Major Repair<br>Minor Repair<br>N/A<br>Monitor<br>Functional | <ul> <li>Fully accessed (walked on) At eaves At ground with binoculars (too steep/ inaccessible) Note: (limitations in effect)</li> <li>LIMITATIONS</li> </ul>   |
| Ë, Ë,  | <ul> <li>☐ Majority of the above elements were snow/ ice/ frost covered.</li> <li>✔ Flat roof is covered with gravel/ decking</li> <li>✔ Due to the unpredictable and latent nature of roof leaks no assurances or warranty can be provided that your roof will not</li> </ul> |
|  | leak within the approximated expected lifespan stated in this report. Ice damming problems are beyond our ability to predict.<br>ROOF COVERINGS TYPE   |
|  | Asphalt shingles are the principal roof covering of the building.  |
|  | Asphalt shingles cover all sloping roof surfaces of the building.  |
|  | Tar/felts; tar and gravel covers the principal flat roof surfaces of the building.   |
|  | is the principal roof covering of the building.  |
|  | Flat roof membrane     covers the roof surface at the     Lower 2nd floor roof   |
|  |  |
|  | ROOF COVERINGS CONDITION (where visible)   |
|  | Estimated remaining lifespan of roof shingles/coverings: INOTE: Estimated lifespan based on visible portion of roof only.  |
|  | Tar and gravel   =   years   ?   |
|  | Shingles and flat roof mambrane       =       8       years       ?         General condition of flat roof coverings:       Good       Image: Fair       Poor       ?  |
|  | General condition of flat roof coverings: □ Good 	 Fair □ Poor □ ?<br>□ Current repair is required at:   |
|  | Roof covering replacement is required at:  |
|  | High probability of replacement of     roof coverings within     years.  |
|  | □ Repairs/ roofing tune-up is required soon/ before next application of roof coverings<br>□ Repairs/ roofing tune-up is required soon/ before next application of roof coverings<br>□ Annual visual inspection required.   |
|  | Trim tree branches/ vines away from roof edge.   |
|  |  |
|  | ROOF/WALL FLASHINGS & JOINTS (where visible)   |
|  | All/most flashings are in 🖉 Good condition 🔲 Fair condition  |
|  | Repair/replace/ install flashings at:  |
|  | Repair/ replace all flashings with next roof covering replacement. Caulking rec'd at:  |
|  | Repairs/ maintenance required before next application of roof coverings: (ie) caulking or tarring <b>ROOF DRAINAGE</b>   |
|  | Type: 🗹 Aluminum 🗌 Galvanized steel 🔲 Plastic 🔲 Copper 🔛 Lead 🔛 Hoppers/Scuppers   |
|  | 🗹 Roof drainage is in: 🗹 Good condition 🗌 Fair condition 🔲 Seasonal cleaning required  |
|  | Gutters Downpipes/ drains require repair/ extending/ painting at:  |
|  | Extend downpipe from upper level roof directly into lower gutter/ eavestrough. 🔲 Repair loose gutters; nails.  |
|  | Extend/ relocate downpipe(s) at corner/ side 4'-6' away from building Add drainage pads  |
|  | Replacement/ Installation of gutters/ downpipes recommended at:  |
|  | Gutters & downpipes are approaching end of functional life. Caulking at leaky joints required.   |
|  |  |
|  | SOFFIT AND FASCIA<br>Type:  Aluminum Plywood Wood Vinyl  |
|  | Soffit & fascia are in: 🗹 Good condition 🗌 Fair condition 📄 Painting of soffit/ fascia required  |
|  | Repairs are required/ recommended at:  |
|  | Constraints Replacement/ new aluminum cladding of soffit/ fascia is recommended in future.  SKYLIGHTS ROOF WINDOWS & SOLARIUMS   |
|  | Type: Factory built Home-made (usually of sub-standard quality)  |
|  | Units are in: Good condition Fair condition Evidence of leakage at:  |
|  | Annual maintenance/ caulking recommended. Repair/ replace:   |
|  |  |

| 1/2-Yr. Priority K   | ey EXTERIOR (GENERAL CONDITIONS)  |  |  |  |  |  |
|--|---|--|--|--|--|--|
| Maj<br>Min<br>N/A<br>Mor<br>Func                             | Approximate age of building is $100$ years. Building has been substantially renovated 8 years ago. $\square$ N/A  |  |  |  |  |  |
| Major Repair<br>Minor Repair<br>N/A<br>Monitor<br>Functional | TYPE OF STRUCTURE CONSTRUCTION TYPE OCCUPANCY TYPE  |  |  |  |  |  |
| epair<br>epair<br>al   | □ Detached  |  |  |  |  |  |
|  | Semi-detached Prick veneer Basement apt. added Triplex  |  |  |  |  |  |
|  | Row house/fully attached Solid masonry Multi-purpose occupancy Fourplex   |  |  |  |  |  |
|  | Condominium/townhouse Wood frame-upper level  |  |  |  |  |  |
|  | Brick front only  |  |  |  |  |  |
|  | EXTERIOR WALLS/WALL COVERINGS   |  |  |  |  |  |
|  | Brick/Masonry (inspected at grade level)  |  |  |  |  |  |
|  | Masonry units & mortar are in: Good condition Fair general condition.   |  |  |  |  |  |
|  | Mortar repair; tuck point recommended at:   |  |  |  |  |  |
|  | Brick repair required at:   |  |  |  |  |  |
|  | Non-structural cracks noted which could/ should be repaired. Repair sills at:   |  |  |  |  |  |
|  | Wall sidings (inspected at grade level)   |  |  |  |  |  |
|  | Type: Aluminum Vinyl Wood Insulbrick Stucco/ EIFS   |  |  |  |  |  |
|  | Good condition Fair general condition. Repair required/ recommended at:   |  |  |  |  |  |
|  | New wall coverings/ re-cladding recommended at:   |  |  |  |  |  |
|  | <ul> <li>Application of protective coatings ( paint/ stain ) recommended to most/ all wood/ other surfaces.</li> <li>Caulking/minor repairs at trimwork:</li> </ul> |  |  |  |  |  |
|  | Foundation Wall (above grade)   |  |  |  |  |  |
|  | Foundation wall is in: 🗹 Good condition 🔲 Fair condition 🔲 Non-structural cracks noted  |  |  |  |  |  |
|  | Requires tuck pointing at:  |  |  |  |  |  |
|  | Requires parging/ repair at:  |  |  |  |  |  |
|  | Chimneys  |  |  |  |  |  |
|  | Type:  ✓ Masonry  |  |  |  |  |  |
|  | Good condition 🖉 Fair condition 🔲 Requires repair/ tuck pointing 🔲 Flue cap recommended   |  |  |  |  |  |
|  | Requires new chimney cap/ drip edge Requires rebuilding/extending Remove obsolete chimney   |  |  |  |  |  |
|  | Exterior Doors  |  |  |  |  |  |
|  | Exterior doors at: 🗹 Front 🗌 Side 🗹 Rear are in: 🗹 Good condition 🔲 Fair condition  |  |  |  |  |  |
|  | Repair/ replace:  |  |  |  |  |  |
|  | Install storm/ screen door at:  |  |  |  |  |  |
|  | Upgrade/ caulking/ painting Upgrade weather stripping Upgrade locks at:   |  |  |  |  |  |
|  | Windows (General)   |  |  |  |  |  |
|  | Material Type: Aluminum Wood 🗹 Vinyl trim   |  |  |  |  |  |
|  | Predominant styles: Single/Double-hung 🗹 Casement Sashless 🗹 Horizontal sliding   |  |  |  |  |  |
|  | Windows are in: 🗹 Good condition 🗌 Fair condition 🔲 Upgrade caulking/ painting  |  |  |  |  |  |
|  | Storm/ screen systems are recommended to be upgraded at: middle bedroom   |  |  |  |  |  |
|  | Repair/ replace window frame/ sills at  |  |  |  |  |  |
|  | Window refurbishing/ replacement recommended:   |  |  |  |  |  |
|  | GRADING/SITE DRAINAGE/RETAINING WALLS   |  |  |  |  |  |
|  | Good condition 🖉 Fair grading conditions exist alongside the foundation(s) of the building.   |  |  |  |  |  |
|  | Grading conditions require improvement at: Front Rear Side Patio/ walkway slopes toward wall<br>Retaining walls are in: Good condition Fair condition               |  |  |  |  |  |
|  | Retaining walls require repair/ replacement at:   |  |  |  |  |  |
|  | Window wells are in:  Good condition Fair condition   |  |  |  |  |  |
|  |   |  |  |  |  |  |
|  | Window well repair/ install at:   |  |  |  |  |  |
|  | See Additional Comment Page   |  |  |  |  |  |

| 1/2-Yr. Priority Ke  | y EXTERIOR (GENERAL CONDITION) continued   |
|--|--|
| Majo<br>Mino<br>N/A<br>Mon<br>Func                           | GARAGE/OUTBUILDING/CARPORT   |
| Major Rep<br>Minor Rep<br>N/A<br>Monitor<br>Functional       | Attached Garage Good condition Fair condition Poor condition   |
| Major Repair<br>Minor Repair<br>N/A<br>Monitor<br>Functional | Gas proofing measures of common walls with house required; provide gas seal. Repair holes in walls/ cellings.  |
|  | 🔲 Entry door into dwelling requires self-closing device /repair self-closure. 🔲 Weather stripping/ caulking required to door/ frame.   |
|  | Detached Garage Good condition Fair condition Poor condition/ Remove   |
|  | Structure type: Wood Frame Solid Masonry Brick Veneer Repairs to walls required  |
|  | Roof Coverings   |
|  | Good condition Fair condition Replace roof coverings soon Eavestroughs recommended/ repair/ install  |
|  | Caution: Underground/ overhead wires supplying power to garage/ shed. Electrical power to garage is recommended  |
|  |  |
|  | Overhead Door Operation Good condition Fair condition Requires repair/ replacement/ painting   |
|  | Automatic Door Operation Install dedicated receptacle for garage door opener; avoid extension cord use.  |
|  | Good condition Fair condition Requires repair/ replacement Adjust/ no auto-reverse   |
|  | WALKWAYS/DRIVEWAYS   |
|  | <ul> <li>Good condition Fair condition Replacement of driveway/ walkway recommended.</li> <li>Repair work required/ recommended at:</li> </ul>   |
|  | PORCHES/DECKS/BALCONIES (egress to exterior)   |
|  | Location: Front Type: wood masonry Concrete steel unable to access under deck  |
|  |  |
|  | Structural supports: 🗹 Good condition 🗌 Fair condition 🔲   |
|  | Decking:     Image: Good condition     Fair condition       Standard triang     Fair condition   |
|  | Steps/stairs: $\blacksquare$ Good condition $\blacksquare$ Fair condition $\Box$ <t< th=""></t<> |
|  | Guards/handrails:       Good condition       Fair condition       Guardrails low/ spacing unsafe/ repair/ missing         Location:       Rear       ▼       Type:       ✓ wood       masonry       concrete       steel       unable to access under deck   |
| •••••  |  |
|  | Structural supports: 🗹 Good condition 🗌 Fair condition   |
|  | Decking: Good condition Fair condition   |
|  | Steps/stairs: Good condition Fair condition  |
|  | Guards/handrails: Good condition Fair condition Guardrails low/ spacing unsafe/ repair/ missing  |
|  | Handrail/guardrail recommended alongside steps at:   |
|  |  |
|  | EXTERIOR PLUMBING CONDITIONS Winterized/ could not test.   |
|  | Garden hose connection location: 🗹 Front 🗌 Rear 🗹 Side 🛄 Garage 🛄 None   |
|  | Good condition Fair condition Repair/ replace at:  |
|  | Main vent stack(s)   |
|  | Good condition     Requires repair/ extending from roof  |
|  | Good clearance from windows/ doors 🔲 No evidence of vent stack for plumbing system visible.  |
|  | EXTERIOR ELECTRICAL CONDITIONS   |
|  | Exterior plug receptacle location: 🗹 Front 🔽 Rear 🔲 Side 🔲 Garage  |
|  | ✓ Good condition   |
|  | Requires repair/ replacement at:   |
|  | All/most exterior receptacles are required to be replaced with GFCI type. Rework exposed cabling at exterior walls   |
|  | Lighting location:  Main entrance Side entrance Rear entrance Garage Garage  |
|  | Fixture(s) are in: 🗹 Good condition 🗌 Fair condition   |
|  | Repair/ replace at:  |
|  | Service entrance: (electrical cables feeding house from street transformer)  |
|  | ✓ Overhead entrance Underground/lateral entrance   |
|  | Mast head conduits/ meter base properly affixed to building. Repairs are required at   |
|  |  |

## **Exterior Image**



Front porch re caulking of flashing between slab and foundatioin wall is required



Recaulk flashing-Front porch- possible source of moisture on drywall in ceiling of storage area in bsmt

| 1/2-Yr. Priority Ke  | <b>FOUNDATIONS BASEMENTS &amp; STRUCTURES</b>   |
|--|---|
| Major Repair<br>Minor Repair<br>N/A<br>Monitor<br>Functional | LIMITATIONS:  |
| Major Rep<br>Minor Rep<br>N/A<br>Monitor<br>Functional       | Substantially/partially finished basement/ crawlspace limited observations.   |
| lepai<br>lepai   | Due to the unpredictable and latent nature of basement leaks no assurances or warranty can be provided that your basement will not leak         |
| <u> </u>   | in the future. We caution you that it is common for basement leaks to develop at any time in the future where no such leaks existed in the past |
|  | We cannot detect previous leaking or predict future leaking.  |
|  | We are unable to detect existence or type of mold at interior space. Further investigation is recommended.                                      |
|  | FOUNDATION CONSTRUCTION TYPE  |
|  | Continuous foundation 🔲 Masonry/ wood piers 🔄 Slab on grade 🔲 Wood beam on grade  |
|  | ACCESS/BASEMENT TYPE  |
|  | ✓ Full basement Crawlspace Basement & crawlspace combination Crawlspace fully/partially accessed  |
|  | Crawlspace is interconnected with adjacent dwelling   |
|  | FOUNDATION MATERIAL TYPE  |
|  | Brick Stone Concrete block Poured concrete Preserved wood foundation  |
|  | Foundation wall interiors not accessible for visual inspection. 🔲 Load-bearing components not visually accessible.                              |
|  | Non-structural cracks were observed which could be a source of future water penetration.  |
|  | Above grade portion of foundation wall appear to be poured concrete. No portion of wall is visible in bsmt                                      |
|  | <b>EXTENSION/ADDITION</b> at the <b>Rear</b> is supported with a different foundation type than the main building.                              |
|  | Continuous concrete Masonry/ wood piers Slab on grade Wood beam on grade  |
|  | Crawlspace Full basement No visible accessibility Access to crawlspace is recommended.  |
|  | Repairs/ improvements are required at:  |
|  | INTERIOR COLUMNS & BEAMS/INTERIOR LOAD SUPPORTS (BASEMENT LEVEL)  |
|  | Columns & Walls: Wood Steel Masonry Not visible   |
| C  | Beams: Wood Steel Paralam/Engineered wood Not visible   |
| Copyright CBCG 2016 -  | Support system members are in: Good condition where visible Fair condition where visible  |
| ight   | Repairs to support load are required at:  |
| Ge ₽ □ □ □ □   | FLOOR (BASEMENT)  |
| G 2(   | Concrete Finished (covered; limited observations) Cood condition Fair condition   |
| )16 -  | Unfinished/exposed soil 🔲 Raised wood(limited observations) 🔲 Removal of raised wood sub-floor is recommended.                                  |
| Li   |   |
| nsec   | FLOOR JOISTS/FLOOR SYSTEM   |
| l to I   | Type (floor & ceiling joists where visible)   |
| rade   | ✓ Wood joists   |
| ep S   | Floor system appears to be in: Good condition where visible 🖌 Fair condition where visible  |
| □ □ □ □ □ □ □ □ □ □ □ □ □ □ □ □ □ □ □                        | Some localized repairs/ defects Repair/ replace floor joists at:  |
|  | BASEMENT WINDOWS/VENTILATION & INSULATION   |
| ntil   | Good ventilation 🗹 Fair natural ventilation supplied to basement/ crawlspace.   |
| Nove   | Replacement/ upgrade of all/ some basement windows are recommended.   |
| embe   | Supply ventilation to: Weather strip cold storage room door.  |
| er 15  | Insulation recommended at:  |
| 2020   | WATER SEEPAGE/PENETRATION (visible condition only with use of moisture meter)   |
| 0  | NOTE: A mold/IAQ inspection is recommended in the event of active water leaks/dampness or high humidity levels.                                 |
|  | No visual evidence of active water penetration through foundation walls.  |
|  | Dampness/ efflorescence noted on foundation walls.  |
|  | Active leaking/seeping observed through foundation walls at: Bulkhead -dampness verified with moisture meter                                    |
|  | There is small area of water damage on the drywall of bulkhead in storage area at front of basement   |
|  | Possible major damage to interior finishes as result of ongoing/ previous leaks and moisture. Further review recommended.                       |
|  | Previous leaking/seeping which measured dry observed through foundation walls at:   |
|  | All areas of foundation walls not thoroughly inspected due to finished wall coverings and storage of material/etc.                              |
|  |   |

✓ See Additional Comment Page

## FOUNDATIONS BASEMENTS & STRUCTURES COMMENT PAGE

| Jse of a r | noisture meter verified that a small patch of drywall is damp.   |
|------------|--|
|            | ner has indicated that repair work to the slab was recently completed to address the leak which caused the damp    |
| drywall.   |  |
|            |  |
| wominot    | ion of the exterior of the foundation revealed that the caulking along the flashing between the porch slab and the |
|            | n has lost adhesion to the concrete.   |
| oundation  | n has lost adhesion to the concrete.   |
|            |  |
|            |  |
|            |  |
|            |  |
|            |  |
|            |  |
|            |  |
|            |  |
|            |  |
|            |  |
|            |  |
|            |  |
|            |  |
|            |  |
|            |  |
|            |  |
|            |  |
|            |  |
|            |  |
|            |  |
|            |  |
|            |  |
|            |  |
|            |  |
|            |  |
|            |  |
|            |  |
|            |  |
|            |  |
|            |  |
|            |  |
|            |  |
|            |  |
|            |  |
|            |  |
|            |  |
|            |  |
|            |  |
|            |  |



Moisture damage to drywall on bulkhead in laundry area.

| 1/2-Yr. Priority Ke  | y ELECTRICAL SYSTEM  |
|--|--|
| Major Repair<br>Minor Repair<br>N/A<br>Monitor<br>Functional | LIMITATIONS:   |
| Major Rep<br>Minor Rep<br>N/A<br>Monitor<br>Functional       | Ratio/ percentage of different wiring types are minimums (if provided). Further review by a licensed electrician is required.  |
| kepa<br>kepa<br>nal  | We cannot detect existence of knob & tube wiring behind walls and within junction boxes/outlet boxes.  |
| <b>H</b> , <b>H</b> ,  | Access to main panel is restricted. Could not visually access or open main panel.  |
|  | Auxiliary systems not inspected: back-up generators, solar & battery power, low-voltage lighting, pool and spa systems.  |
|  | MAIN ELECTRICAL STATION  |
|  | Main disconnect rating:         □         60A         ✓         100A         □         125A         □         200A         □         400A         □         A  |
|  | Main panel service rating: 60A 🗹 100A 🗌 125A 🗌 200A 🛄 400A 🔲 A   |
|  | Main power disconnect type: 🗹 Circuit breaker 🔲 Knife switch/cartridge fuse  |
|  | Supply voltage: ☐ 120V 🖉 120V/240V 🖸 347V/600V Service entrance conductors: ☐ Cu 🗌 Al 🗹 Not visible  |
|  | Grounding conductor: 🗹 Good condition 🔲 Not Determined 🔲 Requires repair/replacement   |
|  | Location of main and distribution panels: 🗹 Basement 🔲 Garage 🛄 Attic 🛄 Shed 🔲   |
|  | Location of auxiliary distribution panels:   |
|  | Condition of main/auxiliary panels: 🗹 Good condition 🗌 Fair condition  |
|  |  |
|  | Adequate visited main distribution panel is installed. Labelling of branch circuit panels is recommended.  |
|  | Adequate v number of circuits are available to properly distribute intended load.  |
|  | ✓ distribution panel(s) are recommended(for future use).   |
|  | Spare circuits available at distribution panel: Yes V No spare circuits are available. Auxiliary panel is recommended.   |
|  |  |
|  | Double tapping noted at some circuits Possible overloaded circuit situation. Monitor. DISTRIBUTION Note: Determining branch wiring types is limited to visual inspection only.   |
|  | Predominant visible branch wiring type:  |
|  | □ Knob & tube (old copper)     %    ?  |
|  | BX (metallic sheathed) % ? Aluminum % ? Ungrounded older romex % ?   |
|  |  |
|  | □ Note: Aluminum wiring is the original/principal branch wire type.  ✓ No unsafe conditions identified with outlets tested.  |
|  | BRANCH CIRCUITS OVERCURRENT PROTECTION:  |
|  | At main distribution panel(s): Glass fuses Cartridge fuses   |
|  | At auxiliary panel(s): Glass fuses Cartridge fuses Breakers  |
|  | Fuses/breakers   |
|  | Properly sized fuses/ breakers are presently used to protect branch circuits.  |
|  | Arc fault circuit interrupters (A.F.C.I) are recommended to be installed at panel to protect bedrooms/convenience receptacles.   |
|  | General  |
|  | Good v lighting source is provided to all habitable areas & service rooms.   |
|  | Additional lighting recommended at:  |
|  | Good v number of receptacles is provided to all habitable areas & service rooms.   |
|  | Additional receptacles recommended at:   |
|  | REPAIR/UPGRADING RECOMMENDATIONS   |
|  | <b>Upgrade amperage of main service to:</b> 100 AMPS 200 AMPS presently or upon the next home improvement undertaken.  |
|  | Most/ some convenience receptacles in dwelling do not have secondary ground (i.e. 2 prong); add GFCI receptacles.  |
|  | <b>Rework poor wiring connections at:</b> Basement Garage Attic Panel  |
|  | Repair/replace lighting fixtures/ switches/ ceiling fans at:   |
|  |  |
|  | Repair/replace receptacles at  |
|  | Missing coverplates/ loose outlets/ exposed cabling observed at:   |
|  | □ Installation/maintenance of smoke/CO alarms at all floor levels of the building/dwelling is required. □ A.F.C.I. recommended/ bedrooms.  |
|  | $\Box$ instantation maniferrate of shoke/co atams at an noor reversion the building/dweining is required. $\Box$ A.1.6.1. recommended betrooms.<br>$\Box$ G.F.C.I. receptacles are req'd at: $\Box$ kitchen counter $\Box$ exterior $\Box$ garage/ outbuilding $\Box$ bathrooms $\Box$ spa/ whirlpool bath |
|  |  |

| 1/2-Yr. Priority Ke  | y CENTRAL HEATING SYSTEM-FURNACE/FORCED AIR SYSTEMS  |
|--|--|
| Majo<br>Mino<br>N/A<br>Mon                                   | LIMITATIONS  |
| Major Rep<br>Minor Rep<br>N/A<br>Monitor<br>Functional       | Determining winter comfort with specific areas is beyond the scope of a visual inspection.                                   |
| Major Repair<br>Minor Repair<br>N/A<br>Monitor<br>Functional | The heat exchanger is concealed within the furnace and cannot be reviewed.   |
|  | The outdoor temperature was too high to sufficiently review the heating system/ductwork and winter comfort.                  |
|  | GENERAL COMMENTS   |
|  | Energy source: Oil 🗹 Gas Electric B.T.U rating 45000   |
|  | Furnace type: 🔲 conventional warm air furnace 🔲 mid-efficiency warm air furnace 📝 high-efficiency warm air furnace           |
|  | HWT/Combo system Commercial roof top unit Ground source heat pump Fan/coil unit  |
|  | Bonding wire for gas line is not correctly installed- it should terminate on the house ground.                               |
|  | Approximate age of furnace 1 = 8 years. Approximate age of furnace 2 = years.  |
|  | <b>Probability of furnace 1 replacement within the next</b> 5 years ☐ high ☐ Medium ✔ Low ☐ ?                                |
|  | Probability of furnace 2 replacement within the next years high Medium 2 Low ?   |
|  | Chimney flue interior: Clay lined Metal lined Brick lined I Direct vent Metal lining of flue required.                       |
|  | Furnace room ventilation: 🗹 Good 🔲 Fair  |
|  | Thermostat condition: 🗹 Good 🔲 Requires replacement Thermostat location: 🗹 Good 🔲 Requires relocation                        |
|  | Heat source supplied to habitable areas/zones  |
|  | Basement:  ✓ Yes No Main floor:  ✓ Yes No 2nd floor:  ✓ Yes No 3rd floor:  ✓ Yes No  |
|  | Habitable room(s) not provided with a heat source:   |
|  | WARM AIR SYSTEM-FURNACE Good overall condition Fair overall condition CO emission test required.                             |
|  | Drive/motor operation: 🗹 Good 🗌 Fair 🔲 Requires repair/ replacement  |
|  | Clean air/filtration system: 🗹 Good 🔲 Fair 🔲 Requires repair/ replacement/ upgrade   |
|  | Central humidifier operation: 🗹 Good 🔲 Fair 🔲 Requires repair/ replacement/ removal/ upgrade                                 |
|  | Burner(s)/coil condition: Good Fair Requires repair/ replacement NotVisible  |
|  | Limit and operating controls 🗹 Good 🔲 Fair 🔲 Requires repair/ replacement  |
|  | Venting condition: Code Fair Requires repair/ replacement  |
|  | Annual servicing and cleaning recommended. 🗹 Heating company insurance plan recommended. 🗹 Air duct cleaning is recommended. |
|  | Carbon monoxide (CO) detector is required.(all levels) TSSA inspection tag missing. Further review required.                 |
|  | DISTRIBUTION SYSTEM - AIR DUCT SYSTEM  |
|  | Condition of supply plenum: 🗹 Good 🔲 Fair 🔲 Requires repair  |
|  | Condition of return plenum: 🗹 Good 🔲 Fair 🔛 Requires repair  |
|  | Condition of branch ducts: 🖉 Good 🗌 Fair 🔄 Requires repair   |
|  | Condition of register/grilles: 🖉 Good 🔲 Fair 🔛 Requires repair   |
|  | Condition of return ducts/inlets: 🗹 Good 🔲 Fair 🔛 Requires repair  |
|  | Air flow at supply outlets: 🖉 Good 📃 Fair 📃 Requires repair  |
|  |  |
|  |  |
|  | HEATING FUEL STORAGE DISTRIBUTION SYSTEMS  |
|  | Location of gas shut off/ gas meter/oil tank valve: At front of house  |
|  | Cood condition Paint exterior gas piping Requires repair/ replacement  |
|  | SUPPLEMENTARY HEATING (Cannot substantiate effectiveness of in-floor heating due to the limitations of a visual inspection)  |
|  | Electric heaters/ space heaters/ in-floor heat have been installed at the following areas: rear addition                     |
|  | Supplementary heating is recommended at the following areas:   |
|  | Rooms above unheated space: garages: crawlspaces:  |
|  | NOTE: These rooms may be slightly cooler than other areas of the house during cold winter days.                              |
|  |  |

See Additional Comment Page

| 1/2-Yr. Priority Ke  | Y CENTRAL AIR CONDITIONING SYSTEM   |
|--|---|
| Maj<br>Min<br>N/A<br>Mor                                     | LIMITATIONS   |
| Major Repair<br>Minor Repair<br>N/A<br>Monitor<br>Functional | Z Due to the unpredictable nature of air conditioner failures no opinion can be given to system life expectancy or future performance.  |
| epair<br>epair   | Data plate was missing/ not legible; limited inspection. 🗹 Winterized/covered could not review.   |
|  | <ul> <li>☐ Solariums/ skylight vaults/ lofts/3rd floor levels are difficult to cool. Supplementary cooling may be required.</li> <li>✓ The outdoor temperature was too low to safely activate the air conditioning system. Review prior to transaction closing</li> </ul> |
|  | GENERAL INFORMATION   |
|  | Energy source: 🔲 Electric 📝 Gas 🔲 Combination system  |
|  | System type: 🗹 Split system 🔲 Integral system 🔛 Heat pump 🔛 Condominium supply/fan coil unit  |
|  | Type: 🗹 Air to Air 🗌 Ground source 🗌 Ductless system 🔲 Roof mounted 🔲 Interior water cooled   |
|  | Approximate estimated cooling capacity of system #1 B.T.U.'s or <b>2</b> v tons ?   |
|  | Approximate age of cooling system #1 8 2?   |
|  | Approximate estimated cooling capacity of system #2 B.T.U.'s or tons ?  |
|  | Approximate age of cooling system #2 ?  |
|  | EXTERIOR EQUIPMENT (FOR SPLIT SYSTEMS ONLY)   |
|  | Clear of shrubs or plant growth: 🗹 Yes 🔲 No Unit properly mounted(level) on solid base. 🗹 Yes 🗌 No  |
|  | Unit properly positioned out of direct sunlight: 🗹 Yes 🗌 No   |
|  | Electrical connections satisfactory: 🗹 Yes 🔲 No   |
|  | Condition of condenser fins: 🗹 Good 🔲 Fair 🛄 Cleaning required  |
|  | Condition of insulation of low-pressure refrigerant line (where visibly accessible): 🗹 Good 🗌 Fair 🔲 Repair required  |
|  | INTERIOR EQUIPMENT  |
|  | Condition (operation) of condensate line: 🗹 Good 🔲 Fair   |
|  | Condition of refrigerant lines: 🗹 Good 🔲 Fair   |
|  | Thermostat condition: 🗹 Good condition 🗌 Requires replacement   |
|  | Thermostat location: 🗹 Good location 🗌 Requires relocation  |
|  | INDEPENDENT SYSTEMS/ATTIC MOUNTED UNITS   |
|  | Equipment in well ventilated area: Yes No   |
|  | Condition/operation of blower coil: Good Fair   |
|  | Proper condensate drain connection: Yes No  |
|  | Air duct connections at main unit: Good Fair  |
|  | Air filter condition:       Good       Fair       Cleaning/replacement required         COOLING DISTRIBUTION SYSTEM   |
|  | ✓ Using existing heat ducts (see heat distribution system). □ Using separate air duct system  |
|  | Condition of air duct system: 🗹 Good condition 🔲 Fair condition 🔲 Seasonal duct balancing required.   |
|  |   |
|  | Cooling source supplied to habitable areas/room of:   |
|  | Basement  vest Yes No Main floor vest Yes No 2nd floor vest Yes No 3rd floor yes No   |
|  | Rooms with no cooling outlet: rear addition   |
|  | Functional return-air system on each habitable floor level:   |
|  | Basement  ✓ Yes No Main floor ✓ Yes No 2nd floor ✓ Yes No 3rd floor ✓ Yes No  |
|  | Return-air system is recommended at 2nd/ 3rd level to optimize air flow.<br>GENERAL CONDITIONS  |
|  | System was operating normally at the time of inspection. Check operation of AC prior to transaction closing.  |
|  | System is functioning abnormally; further analysis is required.   |
|  | Manufacturers' warranties appear to have expired on major components; system is in fair overall condition.  |
|  | System/major components are approaching end of expected functional life. Budget for replacement.  |
|  | See Additional Comment Page   |
|  |   |

| 1/2-Yr. Priority Ke  | y INTERIOR PLUMBING SYSTEM   |
|--|--|
| Majo<br>Mino<br>N/A<br>Mon<br>Func                           | LIMITATIONS  |
| Major Rep<br>Minor Rep<br>N/A<br>Monitor<br>Functional       | Visual access to main drain and drains underneath basement floors is restricted. No assurances can be provided regarding proper  |
| Major Repair<br>Minor Repair<br>N/A<br>Monitor<br>Functional | drainage conditions or performance. Sewer back-up is beyond our ability to detect or predict.  |
| - ··   | We are unable to detect/ predict slow leaks in drains and water lines.   |
|  | WATER SUPPLY: Municipal Private SEWAGE DISPOSAL: Municipal Private ?   |
|  | MAIN SHUT-OFF VALVE/LEVER  |
|  | Location: 🗹 Basement Front wall  |
|  | Good condition Fair condition ? Requires repair/ replacement   |
|  | TYPES AND VISIBLE CONDITIONS OF WATER SUPPLY LINES (limitations in effect)   |
|  | Predominant type: Copper piping Galvanized steel ? PEX   |
|  | Visible condition: 🗹 Good condition 🔲 Fair condition   |
|  |  |
|  | Removal of all galvanized water lines is required to increase water flow and pressure to a desirable level.  |
|  | Water pressure: Good water pressure Fair water pressure Poor water pressure  |
|  | Functional flow:   |
|  | Good functional flow to 2 fixtures when used simultaneously. Basement fixtures excluded.   |
|  | Fair functional flow is evident Department of main water service is recommended.   |
|  | TYPES AND VISIBLE CONDITIONS OF INTERIOR WASTE/DRAIN LINES         Predominant type:       □ Cast iron/lead       □ Copper piping       ✓ ABS/plastic       □ Galvanized steel |
|  | Visible condition:  Good condition Fair condition  |
|  | No abnormal drainage conditions were observed with all fixtures.   |
|  | Repairs required to vent stacks at:  |
|  | Replace main cast iron stacks and soil lines upon next renovation to house.  |
|  | Repairs required to main drain lines at:   |
|  |  |
|  | Clogged slow draining fixtures at:   |
|  | Improperly installed fixture drains at:  |
|  | Leaking fixture drains at:   |
|  | Fixtures with fair functional drainage that appear to be improperly vented:  |
|  |  |
|  | BASEMENT/CRAWLSPACE FLOOR DRAIN (visible conditions)<br>□ Good condition  Fair condition  Requires repair/ replacement/ cleaning  Back water valve recommended                 |
|  | Location not determined     Floor drain not installed  |
|  | HOT WATER TANK  Rental Owned ?   |
|  | Energy source: Cas Oil Electric Type: Tank Tankless Combination  |
|  | Hot water tank is in:  Good condition Fair condition Requires repair/ replacement Old; replace   |
|  | Venting condition (gas/oil only): C Good/ fair condition C Metal lining recommended  |
|  | SUMP PUMP/SEWAGE EJECTOR SYSTEMS Could not test/sump dry/inaccessible/too cold outside   |
|  | Condition of sump: □ Good □ Fair condition 	 Requires repair/ replacement unable to access sump pump   |
|  | Operation of pump: ☐ Good ☐ Fair condition ☑ Requires repair/ replacement unable to operate  |
|  | Condition of pump discharge: Social and condition Requires repair/ replacement Add cover to sump pump  |
|  | PRIVATE WATER SOURCE Imitations of visual inspection is in effect.   |
|  | Type: Pond/stream/spring Well Vault/cistern Location   |
|  | Operation of pressure tank: Good Fair condition Requires repair/ replacement   |
|  | Operation of (well) pump: Good Fair condition Requires repair/ replacement   |
|  | <b>PRIVATE SEWAGE DISPOSAL SYSTEM</b> NOTE: Limitations of visual inspection is in effect.   |
|  | Type: Septic system Holding tank Not determined Location:  |
|  | Percolation field free of trees/shrubs: Yes No Not determined Location:  |
|  | ✓ See Additional Comment Page  |

| Unable to access sump pump due to excessive storage in the the closet in which it is located |  |
|--|--|
| Shabe to access sump pump due to excessive storage in the the closet in which it is located  |  |
|  |  |
|  |  |
|  |  |
|  |  |
|  |  |
|  |  |
|  |  |
|  |  |
|  |  |
|  |  |
|  |  |
|  |  |
|  |  |
|  |  |
|  |  |
|  |  |
|  |  |
|  |  |
|  |  |
|  |  |
|  |  |
|  |  |
|  |  |
|  |  |
|  |  |
|  |  |
|  |  |
|  |  |
|  |  |
|  |  |
|  |  |
|  |  |
|  |  |
|  |  |
|  |  |
|  |  |
|  |  |
|  |  |
|  |  |
|  |  |
|  |  |
|  |  |
|  |  |
|  |  |
|  |  |
|  |  |
|  |  |
|  |  |
|  |  |
|  |  |
|  |  |
|  |  |
|  |  |
|  |  |
|  |  |
|  |  |
|  |  |
|  |  |
|  |  |

| 1/2-Yr. Priority Ke  | <b>Y GENERAL INTERIOR ELEMENTS</b>   |
|--|--|
| Ma<br>Min<br>Mc  | LIMITATIONS:   |
| Major Repair<br>Minor Repair<br>N/A<br>Monitor<br>Functional | We are unable to detect or predict damage to interior finishes as result of slow or intermittent water leaks. Mold   |
| Repa<br>Repa<br>r<br>r                                       | detection/indentification and/or analysis is beyond the scope of a visual inspection. Thermal seal failures of   |
|  | thermalpane glass is beyond our ability to detect or predict.  |
|  | WALL & CEILINGS  |
|  | Predominant material type: 📃 Plaster & wood lath 📃 Plaster & gypsum lath 🗹 Drywall 🔲 Wood/paneling   |
|  | General condition of surfaces: Cool condition Fair condition Substantial refurbishing recommended/ paint.  |
|  | Most/ some ceilings/ walls are aged; drywalling over existing surfaces is recommended in the near future.  |
|  | Repair required at:  |
|  | Wall structure type: 🗹 Wood 🔲 Steel 🔲 Masonry & strapping Alternate ceiling type: 🔲 Suspended/ acoustic tile   |
|  | ✓ Water stains noted at kitchen ceiling beside the fridge which were measured dry. Monitoring required.  |
|  | FLOOR COVERINGS  |
|  | Predominant material type: 🗹 Carpet 📝 Hardwood 📃 Wood 🗹 Vinyl 📃 Laminate 📝 Tile/Stone  |
|  | General condition of surfaces: 🗹 No hazardous defects exist(normal wear) 🔲 Substantial refurbishing recommended  |
|  | Repair required at:  |
|  | □ 2nd/ 3rd level floor system was not originally intended for habitable use and is presently limited in its ability to support a normal load.  |
|  |  |
|  | PRIMARY WINDOW OPERATION/CONDITION   |
|  | Function of ventilating windows  |
|  | Good condition Fair condition Minor adjustment most/ some units  |
|  | Major refurbishing/ replacement is recommended:  |
|  |  |
|  | Window glazing/panes:  |
|  | Thermal windows with highly visible defective seals/ condensed panes at:   |
|  | Various cracked glass panes are noted. Most/ some panes are single glass only; improvement recommended   |
|  | Window handles/locks/hardware:   |
|  | Good condition Fair condition Some localized repair/ upgrading/ missing  |
|  | All/most operating windows have insect screens. Few/ most insect screens are required to be repaired/ installed  |
|  | PRIMARY DOOR OPERATION/CONDITION   |
|  | Function of interior doors:  |
|  | ✓ Good condition   |
|  |  |
|  | Door hardware-general conditions:  |
|  | ✓ Good condition   |
|  | STAIRWAYS/RAILINGS & BALCONIES   |
|  | Condition of primary staircase(s): Limited headroom and/ or clearances.  |
|  | Good condition 🔲 Fair condition 🔲 Loose treads/ minor repair 🔛 Major repair/ replacement recommened  |
|  | Condition of primary railings/guards:  |
|  | Cood condition Fair condition Loose rails/ spindles/ minor repair  |
|  | Installation of safety handrail recommended/ upper flight only Guardrails too low/ spindle spacing unsafe/ missing   |
|  | Condition of basement staircase(s): Limited headroom/ clearances.  |
|  | Good condition Fair condition Loose treads/ minor repair Major repair/ replacement recommened  |
|  | Condition of basement railings/guards:<br>✓ Good condition   |
|  | <ul> <li>Good condition</li> <li>Fair condition</li> <li>Loose rails/ spindles/ minor repair</li> <li>Installation of safety handrail recommended/ upper flight only</li> <li>Guardrails too low/ spindle spacing unsafe/ missing</li> </ul> |
|  | Condition of 3rd floor/supplementary staircase(s):   |
|  |  |
|  | Good condition Fair condition Loose treads/ minor repair Major repair/replacement recommend  |
|  | Condition of 3rd floor/supplementary railings/guards:  |
|  | Good condition Fair condition Loose rails/ spindles/ minor repair Installation of safety handrail recommended/ upper flight only Guardrails too low/ spindle spacing unsafe/ missing   |
|  | See Additional Comment Page  |
|  |  |

| 1/2-Yr. Priority Ke  | y ATTIC/ROOF SPACES  |
|--|--|
| Maj<br>Min<br>N/A<br>Mon                                     | LIMITATIONS:   |
| Major Rep<br>Minor Rep<br>N/A<br>Monitor<br>Functional       | The inspection process cannot predict the ability of the roof stucture to support heavy snow loads.  |
| Major Repair<br>Minor Repair<br>N/A<br>Monitor<br>Functional | Could not access attic due to seized cover/ no attic access/ further review is required prior to proceeding.   |
|  | Attic reviewed at hatch access. Floor not walked on. All attic spaces were not fully inspected.  |
|  | ACCESSIBILITY  |
|  | Good/ fair access to attic Attic floor walked on Attic has lofting potential   |
|  | Attic roof space has been converted into living space 🔲 Attic interconnected with adjacent dwelling. Install firewall/fire separation.   |
|  | No access to attic is installed Access not required Access to roof spaces/ knee wall spaces is recommended.  |
|  | Relocate access Increase size of attic access Insulate/ weatherstrip hatch Additional access required.   |
|  | VENTILATION  |
|  | ✓ Domed roof units ✓ Soffit vents Gable/ridge vents Attic fan(s)/ turbine vents Spaced board sheathing   |
|  | <b>Roof vent(s):</b> ✓ Good condition  |
|  | Additional vents recommended at soffit/ ridge area Soffit baffles to be installed in the attic at eaves section.   |
|  | INSULATION   |
|  | Approx. R-value:         R0 to R15 (0-5)         R20 to R28 (6-8)         R32 to R40 (10-12)         R40+  |
|  | Type: Cellulose fibre Fibre glass batts/ loose fill Rock wool Vermiculite  |
|  | 🗌 Additional insulation recommended to be installed on the attic floor. 🔲 Additional insulation recommended around air ducts.  |
|  | Insulation is unevenly distributed on attic floor. Add/ redistribute insulation. Evidence of vapor retarders:  |
|  | ROOF STRUCTURES (where visible)  |
|  | Type: 🗌 Rafters/ Collar ties 🔲 Trusses 🔲 Good condition 🔛 Fair condition 🔲 Some localized repairs/ defects   |
|  | Additional collar ties/ structural support is recommended.   |
|  | ROOF BOARDS/SHEATHING (where visible)  |
|  | Type: Plywood Board sheathing Good condition Fair condition  |
|  | Probability of replacement of some/ most sheathing with next shingle replacement   |
|  | Fair/ poor condition due to inadequate ventilation. Possible mold/ mildew residue developing on sheathing.   |
|  |  |
|  | ✓ See Additional Comment Page  |
|  | KITCHEN  |
|  | COUNTER TOP CONDITION  |
|  | Counter top is in: 🗹 Good condition 🗌 Fair condition 🔲 Requires repair/ replacement  |
|  | Localized damage around faucets; counter replacement is imminent.  |
|  | CABINET(S) CONDITION   |
|  | Cabinet condition installation & operation is in 🗹 Good condition 📃 Fair condition   |
|  | Repairs required to drawers/ door fronts/ shelving/ cabinet mounting.  |
|  | STOVE POWER SOURCE   |
|  | Plug receptacle installed/240V Direct wire connection/no receptacle Gas stove connection T.S.S.A tag required Not visible  |
|  | EXTRACTION FAN   |
|  | Exhaust fan is in 🗹 Good condition 🔲 Fair condition 🔲 Repair/ replace fan 🛄 Installation of exhaust fan recommended  |
|  | Re-circulating fan is functional Fan is not vented to exterior   |
|  | ELECTRICAL RECEPTACLES   |
|  | Good/ fair number of receptacles installed at counter level Ungrounded receptacles(s) in kitchen noted   |
|  | Limited number of receptacles in kitchen Additional split duplex receptacles recommended   |
|  | SINK/FAUCET CONDITION  |
|  | Sink is in: Good condition Fair condition Sink requires repair/ replacement  |
|  | Faucet assembly is in       Image: Good condition       Image: Fair condition       Image: Requires repair/ replacement/ new washers/ cartridge         Image: Garborator is in function condition       Image: Repair/ replace garborator       Image: Repair/ replace garborator |
|  | Garborator is in function condition Repair/ replace garborator   |
|  |  |
|  | GENERAL CONDITIONS         The       kitchen is in marginal condition. Major remodelling is recommended in the near future.  |
|  | See Additional Comment Page  |
|  |  |

|   | 1/2-Yr. Priority Ke  | y BATHROOMS  |
|---|--|--|
|   | Majo<br>Mino<br>N/A<br>Mon                                   | LIMITATIONS  |
|   | Major Rep<br>Minor Rep<br>N/A<br>Monitor<br>Functional       | Due to the unpredictable and latent nature of plumbing shower and bathtub enclosure leaks there can be no  |
|   | Major Repair<br>Minor Repair<br>N/A<br>Monitor<br>Functional | assurances or warranty that leaks will not develop at any time after the inspection date. The development of mold  |
|   | <b>-</b>   | is a common result of leaks in the bathroom. We cannot predict or detect damage behind walls.  |
|   |  | SHOWER/BATHTUB ENCLOSURE CONDITION   |
|   |  | <ul> <li>The ceramic tile/wall surfaces are in good general condition.</li> <li>The ceramic tile/wall surfaces are in fair general condition.</li> <li>Sealant and grout touch-ups/ repair required at all/most shower/ bathtub enclosures.</li> </ul> |
|   |  | Shower enclosure exhibits no evidence of leaking but is at the end of expected lifespan at:  |
|   |  | Repair/ replace tile or wall surface at:   |
|   |  | Complete tile and wall replacement required at:  |
|   |  | Repair/ install shower door/ curtain assembly at:  |
|   |  | FAUCETS/SHOWER HEAD CONDITION  |
|   |  | Shower faucets/ head assembly are in good/ fair general condition  |
|   |  | ✓ Tub faucets are in good/ fair general condition  |
|   |  | Shower faucets/ head assembly requires repair/ replacement at:   |
|   |  | Tub faucet requires repair/ replacement at:  |
|   |  | BATHTUB CONDITION  |
|   |  | Bathtubs are in good/ fair general condition Reglazing/re-lining of bathtub recommended at:  |
|   |  | Bathtubs requires repair/ replacement at:  |
|   |  | Whirlpool bath is functional Whirlpool bath requires repair at:  |
|   |  | Whirlpool bath electrical circuit is required to be protected by an accessible GFCI breaker.   |
|   |  | No access panel/ improper access to mechanical equipment at:   |
| Сор   |  | TOILET CONDITION/BIDET CONDITION   |
| Copyright CBCG 2016                                 |  | <ul> <li>Toilets are in good/ fair general condition</li> <li>Toilet requires repair/ replacement at:</li> <li>Toilet is improperly installed to floor (ie) loose at:</li> </ul>   |
| t CB  |  | Bidet in good/ fair general condition Bidet requires repair at:  |
| CG 2  |  | WASH BASINS/FAUCET CONDITION & OPERATION   |
| 2016  |  | ✓ Wash basin are in good/ fair general condition.  |
| - Lic   |  | Wash basin requires repair/ replacement at:  |
| ensec   |  | Faucets are in good/ fair general condition. Faucet washers/ cartridge are to be replaced.   |
| to P  |  | Faucets require repair/ replace at:  |
| 'rade   |  | ELECTRICAL   |
| Licensed to Pradeep Samaroo until November 15, 2020 |  | Receptacles are in functional condition at all/most bathrooms None installed.  |
| marc  |  | Installation of GFCI receptacle recommended at:  |
| o un  |  | Repair/ replace receptacle at:   |
| til No  |  | Repair/relocate light fixture at:  |
| ovem  |  | VENTILATION: WINDOWS/EXHAUST FANS  |
| ber 1   |  | Ventilation is provided by a functional window and/or a functional mechanical exhaust fan.   |
| 5, 20   |  | Repair/replace exhaust fan at:   |
| 20  |  | □ Fan not vented to exterior at: Basement washroom<br>□ Exhaust for installation recommended at:   |
|   |  | Exhaust fan installation recommended at:     Rework window to provide proper operation/replace window at   |
|   |  | Window is located in shower enclosure; protection of window is required at:  |
|   |  | SAUNAS/SPAS/STEAMER  |
|   |  | SAUNAS/SPAS/STEAMER  |
|   |  | System/ components require repair/ replacement at:   |
|   |  | GENERAL CONDITIONS   |
|   |  | The bathroom is in marginal condition. Major remodelling is recommended in the near future.  |

See Additional Comment Page

| 1/2-Yr. Priority Ke  | y FIREPLACES  |
|--|---|
| Maj<br>Min<br>N/A<br>Mor                                     | LIMITATIONS:  |
| Major Repair<br>Minor Repair<br>N/A<br>Monitor<br>Functional | Inspecting condition of flue and ability of fireplace to draw is beyond scope of visual inspection. Camera inspection of flue is rec'd. |
| lepai<br>lepai   | FIREPLACE TYPE  |
| , ,  | Masonry fireplace at:   |
|  | Wood-burning stove at:  |
|  | Factory-built fireplace at:   |
|  | Wood/ coal insert at:   |
|  | Gas fireplace at: TSSA inspection tag missing. Further review required.   |
|  | FIREPLACE CONDITION   |
|  | Combustion chamber is in good/ fair condition.  |
|  | Hearth extension is in good/ fair general condition Smoke chamber is in good/ fair general condition.                                   |
|  | Combustion chamber requires repair at:  |
|  | Damper requires repair/ replacement at:   |
|  | Hearth floor requires repair/ extending at:   |
|  | Smoke chamber requires repair at:   |
|  | Note: Basement fireplace may not draw properly. Alternative repair/ improvement strategy recommended                                    |
|  | Flue cleaning recommended at:   |
|  | Roughed-in fireplace installed at:  |
|  | Non-combustible base/lateral clearances from combustible materials of wood burning stoves.  |
|  | Good condition Fair condition W.E.T.T inspection/ camera inspection of flue recommended.  |
|  | Improvement required at:  |
|  | Do not use fireplace until certified as safe.   |
|  | See Additional Comment Page   |
|  |   |
|  | LAUNDRY ROOM  |
|  | CLOTHES DRYER CONNECTIONS   |
|  | Power source: Plug receptacle 240 V Direct wire; no plug No electrical connections Gas dryer connection Not visible                     |
|  | Dryer venting: Properly vented to the exterior. Duct/ vent requires repair/ cleaning/ repair at exterior No venting installed           |
|  | Replace with metal duct. Vented through window; rework. Exhaust fan laundry room not vented to extr                                     |
|  | WASHING MACHINE CONNECTIONS   |
|  | Power source: Plug receptacle available & properly grounded. No plug receptacle installed/replace receptacle.                           |
|  | Water connections: Satisfactory connections/ shut off valve.  |
|  | Connections require repair/ replacement/ relocating. Replace connection hoses with steel braided lines                                  |
|  | LAUNDRY TUB/FAUCETS Installation recommended  |
|  | Tub is in: Good condition Fair condition Tub requires repair/ replacement   |
|  | Faucet is in: 🔲 Good condition 📄 Fair condition 📄 Faucet requires repair/ replacement 📄 New washers required                            |
|  | EJECTOR PUMP FOR LAUNDRY TUB Good condition Fair condition Pump requires repair/ replacement  |
|  | EUDTHED INCLUDIES TO SELLED OF DOORDTV  |
|  | FURTHER INQUIRIES TO SELLER OF PROPERTY   |
|  | Ask seller for any manufacturer's warranties or service contracts for appliances and equipment and recent home improvements.            |
|  | Ask seller for plans/drawings/project documentation and permits for any improvements to the property.                                   |
|  | Ask seller for list of tradespeople and service technicians who have worked on the property.  |
|  | Inquire to seller about cause of water stain on ceiling/ wall.  |
|  |   |
|  |   |
|  |   |
|  |   |
|  | ▼   |

# ATTIC/ROOISPACES/KITCHEN/FIREPLACES/LAUNDRYROOM

| Flat roof condition does not allow for a visual inspection of the various roofing and attic components     |
|--|
|  |
| Unable to determine where the exhaust fans for the basement washroom and laundry room terminates           |
|  |
|  |
| Bonding wire for the gas line is not correctly installed. It should be attached to the house ground of the |
| city side of the water meter on the water service  |
|  |
|  |
|  |
|  |
|  |
|  |
|  |
|  |
|  |
|  |
|  |
|  |
|  |
|  |
|  |
|  |
|  |
|  |
|  |
|  |
|  |
|  |
|  |
|  |
|  |
|  |
|  |
|  |
|  |
|  |
|  |
|  |
|  |
|  |
|  |
|  |
|  |
|  |
|  |
|  |
|  |
|  |
|  |
|  |
|  |
|  |
|  |
|  |
|  |
|  |
|  |
|  |